

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.:


SKW 6699 T

<u>Parts</u>		<u>Cost (\$)</u>	
1	Wishbone front RH	489.00	BT
2	Ball joint susp	70.00	BT
3	Fixing bolt M14x150 (x2)	16.00	nec
4	Hexagonal nut	15.00	nec
5	SetcolumnscREW	160.00	nec
6	SetcolumnscREW	69.00	nec
7	Cup	57.00	BR
8	Caliper cyl LH	471.00	BR
9	Fixing Bracket	19.00	nec
10	Friction Wheel	319.00	nec
11	Crankshaft seal	83.00	nec
12	Exh Bkt Seal	19.00	nec
13	Fixing clamp Diam 74,5	18.00	nec
14	Screw Diam 6-Lon 20 (x15)	60.00	nec
15	Facing Support RH Ass	202.00	BT
16	Stabilizer (x1)	96.00	BT
17	Tailgate SD sea LH	119.00	nec
18	Window Outside LH	123.00	BT
19	Window Channel LH	261.00	BT
20	Door Fixings (x1)	207.00	nec
21	Door handle LH	346.00	BR
22	Fix Stiffener LH	142.00	BR
23	Passenger side RH AV	2,297.00	DD
24	Door Protector RH	299.00	CUT
25	Door Lock RH	335.00	BT
26	Driver Kit	824.00	nec
27	Fluid Filter	31.00	nec
28	Addition Loom RH	71.00	BR
29	Suspension Arm	215.00	BT
30	R/Anti-Roll Bar	378.00	BT
31	Screw RLX Diam 6x100-14 (x5)	20.00	nec
32	Wtr Outlet Hose	169.00	BT
33	Water pipe	22.00	BT
34	Screw With base M8x125 (x2)	14.00	nec
35	Freon tube	193.00	BT
36	Cat-PF pipe TR PSA K737 F035	2,833.00	BT
37	Exhaust Ft Pipe	267.00	BT
38	Pressure Pipe Entrée	35.00	nec
39	Pressure Pipe Sortie	46.00	nec
40	Adjustment	88.00	nec
41	Slide Cover LH Exterieur	106.00	BR
42	Slide Cover RH Exterieur	106.00	BR
43	Protector	43.00	nec
44	Sound proofing	432.00	BR
45	Caliper Motor	269.00	BR
46	Clamp RH Passager	350.00	BR
47	Clamp LH	350.00	BR
48	Trim LH	69.00	BR
49	Cooling Liquid Drum 2L PAE - 35 (x3)	75.00	nec
50	Cyl head Degas	41.00	nec
51	Balljoint Kit R	187.00	BT
52	Adjustment	88.00	BT
53	Safety belt	757.00	Jam
54	Link	565.00	BT
55	Adjust Collar Stconin 12,5 B6 (x10)	20.00	nec
56	Trim Inf Cent	56.00	BR
Total Parts		15,012.00	
Less Discount 20%		3,002.40	
Total after discount		12,009.60	
57	Bracket, IU Adhesive	26.00	nec
Total Parts		12,035.60	

<u>Labour</u>	<u>Cost (\$)</u>
1 Repair LH & RH wheel housing front & LH front pillar	1,000.00 ✓
2 Replace RH A pillar	1,000.00 ✓
3 Floor bench pulling	500.00 ✓
4 Repair Roof Top panel	500.00 ✓
5 Remove & refit roof lining to facilitate repair	500.00 ✓
6 Repair LH rear wheel housing	500.00 ✓
7 Transfer LH front door attachments	150.00 ✓
8 Transfer RH front door attachments	150.00 ✓
9 Respray front wheel housing LH & RH, Lh front pillar	1,040.00 ✓
10 Respray RH front A pillar	✓ 520.00 ✓
11 Respray roof top	✓ 520.00 ✓
12 Respray LH rear wheel housing	✓ 260.00 ✓
13 Check air bag and seatbelt tensioner warning light on	550.00 ✓
Total Labour	7,190.00
Taxable amount	19,225.60
7% GST	1,345.79
Grand total	\$ 20,571.39

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501

FAX : 6567 5258 / 6565 1240