

ASS. REC. BY: Taufikh

REF:

CS/CT121006442/T19c

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / PP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. SNM21D201213/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 880K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMG8507L Yr Regn: 2018 DecType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mazda 3 HB c.c. 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 39021 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN24A8K0251665Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Turanza

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 8/6/21 07/06/21Survey held at 23 yishun st 51Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

09/06/21 @ 1.46pm revised to Jacqueline Tan via Merimen.

18/08/21 @ 10.28am Taufikh finalised with Derel final fig \$3112.30, 3 days (Red \$5667, 65%)

Date/Time, File Pass to?

☐ : Prell. Report

1) 18/08 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Report Format: MER-TP

Lump Sum / L.B.E. / 3112.30



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME :		WIP : 35803			
3 ANSON ROAD		ADDRESS :		EXCESS :			
#16-00 SPRINGLEAF TOWER				DATE: 19-May-21			
SINGAPORE 079909		TEL :					
ATTN.: MOTOR CLAIMS							
FAX :							
VEH NO :	SMG8507L	DATE IN :		CONTACT PERSON :	RONALD		
CHASSIS NO :	JM6BN24A8K0251665	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL :	MAZDA 3	DATE REG.:		POLICY NO.:			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	REAR BUMPER	MB63C-50-221ABB	1			de✓	\$ 997.50
2	BRACKET, REAR BUMPER	MKD53-50-251	1			?	\$ 5.40
3	RETAINER RHS, REAR BUMPER	MBHN9-50-2H1C	1			?	\$ 37.40
4	RETAINER LHS, REAR BUMPER	MBHN9-50-2J1C	1			?	\$ 37.40
5	GUARD LHS, REAR BUMPER	MB63D-50-371	1			?	\$ 30.60
6	PROTECTOR, REAR BUMPER	MBHN9-50-369	1			?	\$ 58.80
7	TOWING HOOK COVER RHS	MB63B-50-EK1 BB	1			X	\$ 15.80
8	TOWING HOOK COVER LHS	M863B-50-EL1 BB	1			X	\$ 15.80
9	TAPE, PROTECTOR	MGS1D-50-EM1A	2			?	\$ 17.20
10	REAR BUMPER REFLECTOR RHS	MD350-51-5M0E	1			X	\$ 53.00
11	REAR BUMPER REFLECTOR LHS	MD350-51-5L0E	1			X	\$ 53.00
12	REAR BUMPER REINFORCEMENT	MB45C-50-260	1			?	\$ 564.20
13	CLIP, REAR BUMPER	M8GV4-56-145	2			rec✓	\$ 5.80
14	FASTENER, REAR BUMPER	MB45A-56-146A	2			re✓	\$ 6.00
15	RETAINER, SENSOR	MKD47-67-UC5A27	4		?	72-80	\$ 72.15
16	SENSOR, ULTRASONIC	MGMK6-67-UC1 27	2			?	\$ 361.80
17	SENSOR, ULTRASONIC	MKD47-67-UC1 27	2			X	\$ 407.20
18	RIVET, REAR BUMPER	MEA01-50-037	2			rec✓	\$ 16.00
19	GROMMET, REAR BUMPER	M8HN1-50-0Z1A	4			re✓	\$ 10.80
20	T/LAMP GASKET RHS, BODY	M8HP1-51-153	1			re✓	\$ 22.00
21	T/LAMP GASKET LHS, BODY	M8HP1-51-163	1			re✓	\$ 22.00
22	ANTENNA, LF	MKD47-67-6NXA	1			?	\$ 111.10
23	CLIP, ANTENNA	MKD45-67-6NYA	1			?	\$ 2.70
TOTAL PARTS							\$ 2,924.30
TOTAL PARTS COST							\$ 2,924.30
SUPPLEMENTARY							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES

1						
2						
3						
TOTAL PARTS						\$ -
TOTAL PARTS COST						\$ -

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 2,310.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 1,890.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	✓	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X	\$ 330.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUC)	X	\$ 250.00
8	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 5,810.00
TOTAL PARTS	\$ -	\$ 2,924.30
TOTAL	\$ -	\$ 8,734.30
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A		
2	#N/A		

TOTAL LABOUR	\$ -	\$ -
TOTAL PARTS	\$ -	\$ -
TOTAL	\$ -	\$ -
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -

GRAND TOTAL	\$	-	\$	-
-------------	----	---	----	---

REMARKS:

TRANS EUROKARS PTE LTD

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tayfun 97495749
WP 7/6/21

Plp Resurvey before paint
o Zelejs

Tayfun C. Consultants