



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 04/06/2021
TP Veh Reg No: SKQ9981P

Estimate No: ES2100054
Date: 07 Jun 2021
Policy No:
Veh Reg No: SMQ57T
Make/Model: HONDA ODYSSEY 2.4 EXV-S CVT SR
Chassis No: JHMRC1890KC205615
Engine No: K24W72462084
Reg. Date: 07/11/2019

Not Authorized
61 Day @ 5500/h
Recovery After Claim
6 days

Estimate Repair Cost to Vehicle No :SMQ57T

Description	U/Price	Quantity	List Price	Amount
Net Price			SS	SS
1 FRONT TYRE - RH	380.00	1 PC	<i>Sm</i> 380.00	<i>X</i>
2 FRONT WHEEL RIM - RH <i>P-7</i>	800.00	1 PC	<i>new</i> 800.00	<i>600.00</i>
			1,180.00	1,180.00
Spare Parts				
3 FRONT DOOR - RH <i>977.70</i>	1,135.90	1 PC	<i>Ry</i> 1,135.90	<i>✓</i>
4 FRONT DOOR CHANNEL - RH	92.40	1 PC	<i>Sm</i> 92.40	<i>X</i>
5 FRONT DOOR GLASS OUTER MOULDING - RH	147.70	1 PC	<i>Sm</i> 147.70	<i>X</i>
6 FRONT DOOR HINGE - RH (TOP)	188.60	1 PC	<i>R</i> 188.60	<i>X</i>
7 FRONT DOOR HINGE - RH (LOWER)	188.60	1 PC	<i>Dir</i> 188.60	<i>✓</i>
8 FRONT DOOR LOCK - RH	272.80	1 PC	<i>R</i> 272.80	<i>X</i>
9 FRONT DOOR LOCKER PANEL STEP COVER - RH	198.50	1 PC	<i>Sm</i> 198.50	<i>X</i>
10 FRONT DOOR OUTER HANDLE - RH	385.00	1 PC	<i>Sm</i> 385.00	<i>X</i>
11 FRONT DOOR PILLAR - RH	628.60	1 PC	<i>R</i> 628.60	<i>X</i>
12 FRONT DOOR REGULATOR GEAR - RH	278.60	1 PC	<i>Sm</i> 278.60	<i>X</i>
13 FRONT DOOR REGULATOR GEAR MOTOR - RH	334.90	1 PC	<i>Sm</i> 334.90	<i>X</i>
14 FRONT DOOR STICKER - RH	56.50	1 PC	<i>me</i> 56.50	<i>✓</i>
15 FRONT DOOR TRIM BOARD - RH <i>698</i>	698.00	1 PC	<i>my car</i> 698.00	<i>✓</i>
16 FRONT DOOR WEATHERSTRIP - RH	179.50	1 PC	<i>Del / Car</i> 179.50	<i>✓</i>
17 FRONT DOOR OUTER HANDLE - RH	195.50	1 PC	<i>Sm</i> 195.50	<i>X</i>
18 FRONT DOOR PROTECTOR - RH <i>421.90</i>	485.10	1 PC	<i>Ry</i> 485.10	<i>✓</i>
19 REAR SLIDING DOOR - RH	1,112.30	1 PC	<i>R</i> 1,112.30	<i>X</i>
20 FRONT BUMPER	1,227.70	1 PC	<i>R</i> 1,227.70	<i>X</i>
21 FRONT BUMPER FOG LAMP - RH	527.40	1 PCS	<i>Sm</i> 527.40	<i>X</i>
22 FRONT BUMPER FOG LAMP BRACKET - RH	99.40	1 PC	<i>Sm</i> 99.40	<i>X</i>
23 FRONT BUMPER CHROME - RH	168.20	1 PC	<i>CRS</i> 168.20	<i>✓</i>
24 FRONT BUMPER SIDE RETAINER - RH	52.60	1 PC	<i>Sm</i> 52.60	<i>X</i>
25 FRONT FENDER - RH <i>680</i>	780.40	1 PC	<i>Ry</i> 780.40	<i>✓</i>
26 FRONT FENDER INNER SHIELD CLIPS	60.00	1 SET	<i>new</i> 60.00	<i>X</i>
27 FRONT FENDER SPLASH SHIELD - RH	245.30	1 PC	<i>Sm</i> 245.30	<i>X</i>
28 FRONT HEADLAMP - RH	2,245.80	1 PC	<i>Sm</i> 2,245.80	<i>X</i>
29 FRONT LOWER ARM - RH	531.40	1 PC	<i>Ry</i> 531.40	<i>✓</i>
30 FRONT SHOCK ABSORBER - RH	435.80	1 PC	<i>Ry</i> 435.80	<i>✓</i>
31 FRONT DOOR PROTECTOR CHROME - RH	185.15	1 PC	<i>Scr</i> 185.15	<i>✓</i>
32 FRONT FENDER LOWER PROTECTOR - RH <i>210</i>	280.15	1 PC	<i>Del</i> 280.15	<i>✓</i>
33 FRONT DOOR LOWER INNER GARNISH - RH	485.15	1 PC	<i>Repaired</i> 485.15	<i>X</i>
34 FRONT KNUCKLE - RH <i>418.50</i>	680.00	1 PC	<i>Ry</i> 680.00	<i>✓</i>



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 04/06/2021
TP Veh Reg No: SKQ9981P

Estimate No: ES2100054
Date: 07 Jun 2021
Policy No:
Veh Reg No: SMQ57T
Make/Model: HONDA ODYSSEY 2.4
EXV-S CVT SR
Chassis No: JHMRC1890KC205615
Engine No: K24W72462084
Reg. Date: 07/11/2019

Estimate Repair Cost to Vehicle No :SMQ57T

Description	U/Price	Quantity	List Price	Amount
35 DRIVE SHAFT	890.15	1 PC	890.15	890.15
36 STABILIZER LINK	285.15	1 PC	285.15	285.15
Labour				
37 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,000.00	1 JOB	2,000.00	2,000.00
38 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,000.00	1 JOB	2,000.00	2,000.00
39 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	200.00
40 TO REMOVE/REFIT FRONT PILLAR GLASS.	120.00	1 JOB	120.00	120.00
41 TO TOW VEHICLE TO WORKSHOP.	150.00	1 JOB	150.00	150.00
42 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	100.00
43 WHEEL ALIGNMENT	120.00	1 T	120.00	120.00
44 TO REMOVE/REPLACE UNDERCARRIAGE LABOUR.	300.00	1 PC	300.00	300.00
				4,990.00

Total S\$ 21,928.25

Add GST @ 7% 1,534.98

Total Amount Payable S\$ 23,463.23

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND FOUR HUNDRED SIXTY THREE AND CENTS TWENTY THREE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 04/06/2021
TP Veh Reg No: SKQ9981P

Estimate No: ES2100054
Date: 09 Jun 2021
Policy No:
Veh Reg No: SMQ57T
Make/Model: HONDA ODYSSEY 2.4
EXV-S CVT SR
Chassis No: JHMRC1890KC205615
Engine No: K24W72462084
Reg. Date: 07/11/2019

Estimate Repair Cost to Vehicle No :SMQ57T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
Spare Parts				
1 FRONT WHEEL BEARING - RH	185.00	1 PC	185.00	✓
2 FRONT LOWER ARM BALL JOINT- RH 165	180.00	1 PC	180.00	✓
			365.00	365.00
			Total	S\$ 365.00
			GST Amount	S\$ 25.55
			Total Amount Payable	S\$ 390.55

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE