

◀	<	1 of 2 ?	>	▶	↺	↻	100% ▼	📄 ✓	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	----------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD		Ref: CS/SMR21006454/Auf3		
60 WOODLANDS INDUSTRIAL PARK		Date: 07/06/2021		
E4SINGAPORE 757705		Code: SMR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 1447Z	Veh. Inspected	SJF 6162B	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/06/21/5011	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	07/06/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/06/2021	Inspection Date	08/06/2021	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				