



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 06.06.2021
Emailed : 27.10.2021, 10.40am
Date Survey : 08.06.2021

VEHICLE NO : SMH 178 A
MODEL : KIA STINGER 2.0 A
WIP : 34292

Material	:	\$	23,169.60
Labour	:	\$	9,870.00
Sub-Total	:	\$	33,039.60
	:	\$	-
Less Excess	:	\$	300.00
Total	:	\$	32,739.60
GST 7%	:	\$	2,291.77
Grand Total	:	\$	35,031.37
Finalise By/Date	:	<u>LOI / 27/10/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 09/06/2021	Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)
	Reg No/Reg Date	SMH178A / 26/03/2019
	Date In/Mileage	09/06/2021/ 36466
	Chassis/Package	KNAE351AMK606062C
	Engine No	G4KLKH020362
	Make/Model	KIA/STINGER 2.0 A GAA4
	Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	27/10/2021/ 10:19	BLE	260 / AiTing	34292			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 2400.00
REPLACE DAMAGED PARTS, REPLACE LH REAR DOOR, LH REAR FENDER, REAR BUMPER, RH REAR DOOR, LH REAR WHEELHOUSE, REPAIR ROOF PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT98000								✓ 2880.00
RESPRAY ON LH REAR DOOR, LH REAR FENDER, BOOT LID, REAR BUMPER, RH REAR FENDER, RH ROOF, RH REAR DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								
A 54900099								✓ 400.00
REPLACE LH SIDE CURTAIN AIR BAG, LH FRONT SEAT AIR BAG, SENSOR, AND ALL OTHER ATTACHED PARTS								
E PNT88000								✓ 120.00
REMOVE & REINSTALL LH REAR DOOR COMPONENTS TO NEW PANEL								
E PNT88000								✓ 120.00
REMOVE & REINSTALL RH REAR DOOR COMPONENTS TO NEW PANEL								
A 13900099								✓ 400.00
REMOVE & REINSTALL FUEL TANK ASSY TO FACILITATE REPAIR								
E PNT88000								✓ 400.00
REMOVE & REINSTALL REAR FLOOR BOARD, CARPET, SEATS, & TRIMS TO FACILITATE REPAIR								
E PNT88000								✓ 200.00
REMOVE & REINSTALL ROOF LINING TO FACILITATE REPAIR								
A 54900099								✓ 30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								✓ 120.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								
E PNT88000								? 500.00
CONDUCT CHASSIS ALIGNMENT USING CELETTE BENCH								
A WHEELALIGNMENTBP								✓ 120.00
CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								
A 34900099								✓ 400.00
REPLACE LH REAR UNDERCARRIAGE PARTS								

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMH178A / 26/03/2019</td></tr> <tr> <td>Date In/Mileage</td><td>09/06/2021/ 36466</td></tr> <tr> <td>Chassis/Package</td><td>KNAE351AMK606062C</td></tr> <tr> <td>Engine No</td><td>G4KLKH020362</td></tr> <tr> <td>Make/Model</td><td>KIA/STINGER 2.0 A GAA4</td></tr> <tr> <td>Colour/Trim</td><td>H4R HICHROMA RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)	Reg No/Reg Date	SMH178A / 26/03/2019	Date In/Mileage	09/06/2021/ 36466	Chassis/Package	KNAE351AMK606062C	Engine No	G4KLKH020362	Make/Model	KIA/STINGER 2.0 A GAA4	Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK
Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)														
Reg No/Reg Date	SMH178A / 26/03/2019														
Date In/Mileage	09/06/2021/ 36466														
Chassis/Package	KNAE351AMK606062C														
Engine No	G4KLKH020362														
Make/Model	KIA/STINGER 2.0 A GAA4														
Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK														
09/06/2021															

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	27/10/2021/ 10:19	BLE	260 / AiTing	34292			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 34900099								600.00
REPLACE RH REAR UNDERCARRIAGE PARTS								80.00
E PNT88000								40.00
REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR								80.00
M SUNDRY								40.00
APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY								40.00
SUPPLY BODY PANEL SEALANT								40.00
M SUNDRY								30.00
SUPPLY C&C BADGE								400.00
M SUNDRY								480.00
SUNDRIES								30.00
A 34900099								
REPLACE REAR AXLE ASSY								
S SPECIALISTJOB								
SUPPLY GOOD YEAR TIRE 225/45R18								
S SPECIALISTJOB								
REPLACE LH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								-300.00
X EXC								
EXCESS								
X PANEL ASSY-REAR DOOR,RH					1.00	911.00	20.00	728.80
X MOULDING ASSY-RR DR FRAME,RH					1.00	69.00	20.00	55.20
X W/STRIP ASSY-RR DR BELT O/S RH					1.00	45.00	20.00	36.00
X PANEL ASSY-REAR DOOR,LH					1.00	911.00	20.00	728.80
X MOULDING ASSY-RR DR FRAME,LH					1.00	69.00	20.00	55.20
X PAD-FR DR O/S HDL HINGE,LH					1.00	5.00	20.00	4.00
X HANDLE-REAR DOOR OUTSIDE,LH					1.00	31.00	20.00	24.80
X COVER-RR DR O/S HDL,LH					1.00	17.00	20.00	13.60
X PAD-DOOR O/S HANDLE REAR,LH					1.00	5.00	20.00	4.00
X COVER-RR BUMPER					1.00	639.00	20.00	511.20
X BRACKET-RR BUMPER RAIL LWR,LH					1.00	29.00	20.00	23.20
X COVER-RR BUMPER LWR					1.00	342.00	20.00	273.60

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 09/06/2021	Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG
	Reg No/Reg Date	SMH178A / 26/03/2019
	Date In/Mileage	09/06/2021/ 36466
	Chassis/Package	KNAE351AMK606062C
	Engine No	G4CLKH020362
	Make/Model	KIA/STINGER 2.0 A GAA4
	Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	27/10/2021/ 10:19	BLE	260 / AiTing	34292
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X LAMP ASSY-REAR R/REFL,LH		1.00	✓ 29.00	20.00	23.20
X RETAINER		6.00	✓ 2.00	20.00	9.60
X BRACKET ASSY-RR BUMPER SIDE,LH		1.00	✓ 64.00	20.00	51.20
X LAMP ASSY-REAR COMB OUTSIDE,LH		1.00	✓ 908.00	20.00	726.40
X EMBLEM-STINGER		1.00	✓ 68.00	20.00	54.40
X PANEL ASSY-QUARTER OUTER,LH		1.00	✓ 1955.00	20.00	1564.00
X PANEL ASSY-FULL FILLER DOOR		1.00	✓ 53.00	20.00	42.40
X HOUSING-FUEL FILLER DR		1.00	✓ 47.00	20.00	37.60
X OPENER ASSY-FUEL FILLER DR		1.00	✓ 74.00	20.00	59.20
X GUARD-REAR WHEEL,LH		1.00	✓ 159.00	20.00	127.20
X GARNISH ASSY-C.PILLAR,LH		1.00	✓ 183.00	20.00	146.40
X FILLER NECK & HOSE ASSY		1.00	✓ 336.00	20.00	268.80
X FILM-RR DR ANTI CHIPPING,LH		1.00	✓ 15.00	20.00	12.00
X FILM-RR DR ANTI CHIPPING,RH		1.00	✓ 15.00	20.00	12.00
X FILM-ANTI CHIPPG LH		1.00	✓ 23.00	20.00	18.40
X FILM-ANTI CHIPPG RH		1.00	✓ 23.00	20.00	18.40
X RR ARM ASSY-RR UPR LH		1.00	✓ 118.00	20.00	94.40
X ARM COMPLETE-RR UPR FRT		1.00	✓ 118.00	20.00	94.40
X ARM ASSY-RR ASSIST,LH		1.00	✓ 162.00	20.00	129.60
X ARM COMPLETE-RR LWR,LH		1.00	✓ 164.00	20.00	131.20
X HUB ASSY-FR WHEEL		1.00	✓ 520.00	20.00	416.00
X SHOCK ABSORBER ASSY-REAR		1.00	✓ 215.00	20.00	172.00
X CARRIER ASSY-DIFFERENTIAL		1.00	✓ 2506.00	20.00	2004.80
X WHEEL ASSY-ALUMINIUM LHR		1.00	✓ 1054.00	20.00	843.20
X VALVE-TPMS		1.00	✓ 137.00	20.00	109.60
X HEADLINING ASSY		1.00	✓ 2383.00	20.00	1906.40
X CURTAIN AIR BAG MODULE,LH		1.00	✓ 1265.00	20.00	1012.00
X SENSOR ASSY-PRESS TYPE CRASH		1.00	✓ 115.00	20.00	92.00
X SENSOR ASSY-A TYPE CRASH		2.00	✓ 96.00	20.00	153.60
X S/BELT ASSY-FR LH		1.00	✓ 420.00	20.00	336.00
X S/BELT ASSY-FR RH		1.00	✓ 420.00	20.00	336.00
X SEAT BELT PRETENSIONER,LH		1.00	✓ 194.00	20.00	155.20
X SEAT BELT PRETENSIONER,RH		1.00	✓ 194.00	20.00	155.20

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMH178A / 26/03/2019</td></tr> <tr> <td>Date In/Mileage</td><td>09/06/2021/ 36466</td></tr> <tr> <td>Chassis/Package</td><td>KNAE351AMK606062C</td></tr> <tr> <td>Engine No</td><td>G4CLKH020362</td></tr> <tr> <td>Make/Model</td><td>KIA/STINGER 2.0 A GAA4</td></tr> <tr> <td>Colour/Trim</td><td>H4R HICHROMA RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)	Reg No/Reg Date	SMH178A / 26/03/2019	Date In/Mileage	09/06/2021/ 36466	Chassis/Package	KNAE351AMK606062C	Engine No	G4CLKH020362	Make/Model	KIA/STINGER 2.0 A GAA4	Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK
Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)														
Reg No/Reg Date	SMH178A / 26/03/2019														
Date In/Mileage	09/06/2021/ 36466														
Chassis/Package	KNAE351AMK606062C														
Engine No	G4CLKH020362														
Make/Model	KIA/STINGER 2.0 A GAA4														
Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK														
09/06/2021															

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	27/10/2021/ 10:19	BLE	260 / AiTing	34292
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X S/BELT ASSY-RR,LH		1.00	✓ 398.00	20.00	318.40
X S/BELT ASSY-RR,RH		1.00	✓ 398.00	20.00	318.40
X PANEL COMPL-COMB LAMP HSG,LH		1.00	✓ 281.00	20.00	224.80
X BACK ASSY-FR SEAT,LH		1.00	✓ 2661.00	20.00	2128.80
X BOLT	→ Supp.	1.00	10.00	20.00	8.00
X CROSSMEMBER COMPL-RR	→ Quoted under labour line	1.00	? 1648.00	20.00	1318.40
X PARKING BRAKE-ELECTRONIC,LH		1.00	684.00	20.00	547.20
X SHAFT ASSY-DRIVE RR,LH		1.00	1270.00	20.00	1016.00
X GARNISH ASSY-REAR COMB OUTSIDE		1.00	52.00	20.00	41.60
X UNDER COVER ASSY-FLOOR RR,LH		1.00	136.00	20.00	108.80
X BRACKET-RR O/S HANDLE SUPPORT,		1.00	8.00	20.00	6.40
X PANEL ASSY-QUARTER INNER,LH	→ Quoted under labour line	1.00	? 884.00	20.00	707.20
X GRILLE ASSY-AIR EXTRACTOR		1.00	35.00	20.00	28.00
X TRIM ASSY-CTR PILLAR LWR LH		1.00	70.00	20.00	56.00
X TRIM ASSY-CTR PILLAR UPR LH		1.00	222.00	20.00	177.60
X CUSHION ASSY-LWR		1.00	2.00	20.00	1.60
X FASTENER-T/GATE GLASS		2.00	1.00	20.00	1.60
X CLIP		10.00	1.00	20.00	8.00
X BACK SIDE ASSY-RR SEAT,LH		1.00	467.00	20.00	373.60
X BACK SIDE ASSY-RR SEAT,RH		1.00	467.00	20.00	373.60
X RETAINER		1.00	2.00	20.00	1.60
X RETAINER		5.00	2.00	20.00	8.00
X CUSHION ASSY-LWR		1.00	2.00	20.00	1.60
X MODULE ASSY-AIR BAG CONTROL		1.00	810.00	20.00	648.00
X ARM ASSY-RR TRAILING ARM,LH		1.00	? 156.00	20.00	124.80
X CARRIER ASSY-REAR AXLE,LH		1.00	? 636.00	20.00	508.80
X CAP ASSY-FUEL FILLER		1.00	26.00	20.00	20.80
X BOLT		1.00	10.00	20.00	8.00
X CANISTER ASSY		1.00	170.00	20.00	136.00
X MOULDING-WINDSHIELD GLASS		1.00	92.00	20.00	73.60
X LAMP ASSY-SIDE REFLEX REFLECTO		1.00	✓ 35.00	20.00	28.00
X MOULDING ASSY-W/SHLD SIDE,RH	→ Supp.	1.00	94.00	20.00	75.20
Z TEXT					

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG Reg No/Reg Date SMH178A / 26/03/2019 Date In/Mileage 09/06/2021/ 36466 Chassis/Package KNAE351AMK606062C Engine No G4CLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK
09/06/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	27/10/2021/ 10:19	BLE	260 / AiTing	34292

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
AIG OD CLAIM DOA : 06.06.21 SURVEYOR STEVE LKK 08.06.21 POLICY NO : 1900077935-01 REPAIR 14 DAYS Pro Forma <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	23,169.60		Nett	32,739.60
Labour	9,170.00	7% GST on	32739.60	2291.77
Standard Menu	0.00			
Specialist Job	510.00		Total Payable	35,031.37
Diagnostics Job	0.00			
Sundry/Others	-110.00			
Total(w/o GST)	32,739.60			

**This is not an official tax invoice.
This is a computer generated document, no signature is required.**

INSURANCE CO.: **AIG**

Supplementary Parts For Registration No.: **SMH 178 A**

	<u>Materials</u>	<u>Cost (\$)</u>
1	Bolt	10.00 — nec
2	Parking Brake-electronic, LH	684.00 — BR
3	Shaft assy-Drive RR, LH	1,270.00 — BT
4	Garnish assy-Rear comb outside	52.00 — BR
5	Under cover assy-Floor RR, LH	136.00 — BR
6	Bracket-RR O/S handle support	8.00 — BR
7	Grille assy-Air extractor	35.00 — BR
8	Trim assy-Ctr pillar Lwr LH	70.00 — BR
9	Trim assy-Ctr pillar UpR LH	222.00 — BR
10	Cushion assy-Lwr	2.00 — nec
11	Fastener-T/gate glass (x2)	2.00 — nec
12	Clips (x10)	10.00 — nec
13	Back side assy-RR seat, LH	467.00 — CRV
14	Back side assy-RR seat, RH	467.00 — CRV
15	Retainer	2.00 — nec
16	Retainer (x5)	10.00 — nec
17	Cushion Assy-Lwr	2.00 — nec
18	Module assy-Air Bag control	810.00 — nec
19	Cap assy-Fuel filler	26.00 — CVT
20	Bolt	10.00 — nec
21	Canister assy	170.00 — BR
22	Moulding-windshield glass	92.00 — nec
23	Moulding assy-W/shld side, RH	94.00 — BT
Total Materials		4,651.00
Less 20% discount		930.20
Total after discount		3,720.80

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace rear axle assy	400.00 —
2	Supply GoodYear tire 225/45R18	480.00 —
Total labour		880.00
Total amount		4,600.80
7% GST		322.06
Grand total		\$ 4,922.86

Thank You.

Yours faithfully

LOI AI TING

SENIOR OFFICER - ADMIN

KIA SERVICE CENTRE

DID : 6568 4556 / 6568 4501

FAX : 6567 5258 / 6565 1240

CAR NO: SMH 178A

WIP: 34292

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	ELCA CAPPER	? / SUPP		✓	52710 J5000
2	HYD PRESS (W/MT. HUB)	? / SUPP		✓	52750 J5500
3	RR ARM ASSY - RR UPFR. LH	? / SUPP		✓	
4	ARM COMPLETE - RR UPFR FRNT	? / SUPP		✓	
5	ARM ASSY - RR ASSIST, LH	? / SUPP		✓	
6	ARM COMPLETE - RR LWR, LH	? / SUPP		✓	
7	CARRIER ASSY - DIFFERENTIAL	? / SUPP		✓	
8	ARM ASSY - RR TRAILING ARM LH	? / SUPP		✓	STUCK
9		? / SUPP		✓	20/9/21
10	REMOVE & REFM FIND WINDING \$ 240	? / SUPP		✓	
11	WILDER BEALAND	? / SUPP			
12	SHOCK ABSORBER ASSEMBLY - REAR -	? / SUPP			
13	REAR COMEBER ARAY	? / SUPP		✓	
14	FEEL ARM - RCK (PIPE)	? / SUPP		✓	
15	FEEL FUEL CONSTER	? / SUPP		✓	
16	HAND BRAKE MOTOR	? / SUPP		✓	
17	GLASS WLDG	? / SUPP		✓	26130 J5000 Taken
18	WAS SHIPSON	? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: 571N6DM

SURVEYOR: STK

CAR NO: SMH178A

WIP: 34292

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	LHR WHEELHOUSING PINL	? / SUPP		✓	
2	LHR FENDER OUTER MILDG	? / SUPP		✓	
3	LHR UNDER COVER	? / SUPP		✓	
4	LH TAILLAMP GARNISH	? / SUPP		✓	
5	LH REAR FENDER AIR VENT	? / SUPP		✓	
6	LHR DOOR OUTER HANDLE BRKT	? / SUPP		✓	
7	LHR DOOR INNER LOCK	? / SUPP		✓	
8	LH RR SEAT SIDE CUSHION	? / SUPP		✓	
9	RH RR SEAT SIDE CUSHION	? / SUPP		✓	
10	LHR DOOR TRIM	? / SUPP		✓	
11	LHR POOL LOCK CATCH	? / SUPP		✓	
12	CENTRE PILLAR TRIM (TOP)	? / SUPP		✓	
13	(BOTTOM)	? / SUPP		✓	
14	TAILLAMP CLIPS	? / SUPP		✓	
15	TAILLAMP CLIPS	? / SUPP		✓	
16	B clip	? / SUPP		✓	
17	Knocker Ass'y LHR	? / SUPP		✓	
18	wheel Hub Assy LHR	? / SUPP		✓	
19	bolt lps.	? / SUPP		✓	
20	Shock Absorber Rear	? / SUPP		✓	

MODEL: STINGER

SURVEYOR: STEVE

	DATE	TAKEN BY
PHOTO BEFORE PAINT	31/8	EDM
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

Work Order: R001543
 License: smh 178 a
 Technician: 810119 kfsan
 Mileage: 36483
 Date: 6.10.21 11:38

Kia : Stinger : All Wheel Drive (Standard Suspension) : with 17", 18" Wheel : 2017- (CK)

Front : Left

Actual	Before	Specified Range
0°59'	0°59'	-1°00' 0°00'
6°21'	6°21'	6°24' 7°24'
0°04'	0°03'	0°00' 0°12'
14°16'	14°16'	
13°18'	13°18'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°54'	0°54'	-1°00' 0°00'
7°24'	7°24'	6°24' 7°24'
0°08'	0°08'	0°00' 0°12'
12°28'	12°28'	
11°34'	11°34'	

Front

	Actual	Before	Specified Range
Cross Camber	-0°04'	-0°04'	
Cross Caster	-1°03'	-1°03'	
Cross SAI	1°48'	1°48'	
Total Toe	0°12'	0°11'	0°00' 0°24'
Cross Turn Diff.			

Rear : Left

Actual	Before	Specified Range
-1°25'	-1°24'	-2°00' -1°00'
0°14'	0°14'	0°06' 0°18'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°41'	-1°42'	-2°00' -1°00'
0°14'	0°14'	0°06' 0°18'

Rear

	Actual	Before	Specified Range
Cross Camber	0°17'	0°17'	
Total Toe	0°26'	0°27'	0°12' 0°36'
Thrust Angle	0°00'	0°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



Stinger(CK)/2019/G 2.0 T-G..

VCI 3.2



Fault Code Searching

Rescan

Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESHIFTER	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0255

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0195

OS Ver.

Android 10