

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH7294E

02/06/21

MAKE :

MODEL HYU- I40

Type

CHIANG/NTUC

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER		\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH	\$35.60	\$71.20
10	REAR BUMPER CLIPS	\$2.20	\$22.00
2	REAR BUMPER REFLECTOR LH/RH	\$32.00	\$64.00
1	REAR BUMPER UNDER COVER		\$228.00
	SUB TOTAL		\$1,491.20
	20.00%	1128	\$298.24
	DISCOUNTED TOTAL	902.40	\$1,192.96
1	REVERSE SENSOR 10%	5	\$135.70
1	REAR BUMPER MAT		\$50.00
		172.13.3	\$172.13
	Labour Charge		
	Panel Beating	280	\$480.00
	Spray Painting Charge	250	\$300.00
	Remove/refix reverse sensor	30	\$60.00
	Tuff Kote	560	\$60.00
	Check Lighting	wn x	\$60.00
		wn x	\$60.00
	TOTAL LABOUR	1634.53	\$960.00
	ESTIMATE TOTAL	402.1300	\$2,325.09
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanpha 97495749 Duration

WP 3/6/21 @ 415, n

2 days

c/s Repair after repair
Tanpha e Khantow