

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

SATAR ABDUL KADIR
Blk 3 Kaki Bukit Road 1
03 - 04 Eunoss Technolink
Singapore 415935

09th JUNE 2021

TP AXA
Ceilia

SMV6314K

WDD2053422F358762

Accident date: 04th JUNE 2021

Estimated repair cost for vehicle no:  MERCEDES BENZ C200 AMG LINE A 2016

S/n	Qty	Items/Nett	U/price	Amount
				\$2,150.00 +
1	1	Bonnet		\$188.20 +
2	1	Bonnet inner rubber		\$105.00 +
3	1	bonnet logo		\$325.00 +
4	1	bonnet inner lock		\$570.00 +
5	2	Front head lamp	2855	\$185.00 ✓
6	1	Front grille emble logo		\$400.00 ✓
7	1	Front grille		\$255.00 +
8	1	Front grille garnish -centre		\$258.00 +
9	1	Front grille garnish -lower		\$1,852.00 ✓
10	1	Front bumper		\$50.00 ✓
11	10	Front bumper clips	\$5.00	\$50.00 ✓
12	2	Front Bumper Side Bracket	\$185.00	\$370.00 +
13	1	Front Bumper number plate garnish		\$122.00 ✓
14	1	Front bumper number plate		\$50.00 ✓
15	1	Front bumper center lower garnish		\$255.00 ✓
16	2	Front bumper lower side garnish	\$155.00	\$310.00 ✓
17	1	Front bumper inner sponge		\$285.00 ✓
18	2	Front Bumper Side fog lamp chrome	\$122.00	\$244.00 +
19	2	Front Bumper Side lower moulting	\$112.00	\$224.00 +
20	1	Front bumper reinforcement		\$755.00 +
21	2	Front bumper reinforcement lower bracket	\$218.00	\$436.00 +
22	1	Front Bumper Lower Grille		\$450.00 ✓
23	1	Front bumper lower cover		\$485.00 +
24	1	front bumper wiper motor assy		\$1,450.00 +
25	1	radiator assy		\$1,350.00 +
26	1	radiator fan motor		\$1,850.00 +
27	1	air cond condenser		

2855
850(SN)

155.
145.

5864 SN:850

Subtotal :- \$18,254.60

Labour charges
Tuff kote

5277.60

\$120.00 X

\$80.00 30

To Check Wiring System

\$280.00 X

To remove & refill aircond, radiator & top up gas

\$800.00 400

680

\$800.00 250.

LKK Auto Consultants hence notify
the Repairer of the following:

- Panel beating
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Spray painting
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Subtotal :- \$2,080.00

Total:- \$20,334.60

total: 6807.60

h/s: SHK
03 Days.

Acknowledged by Repairer

Signature:

Date:

6K