

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SMK1146U  
Chassis No:  
Engine No:

Report No :  
Date : 02.02.2021

### Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	Damaged 745.20	\$ 934.00	\$ 840.60
2	1	Front Bumper Bracket Right	Necessary	\$ 60.00	\$ 54.00
3	1	Front Bumper Grille with Chrome	Damaged	\$ 496.00	\$ 446.40
4	1	Front Bumper Sensor (1set)	Faulty 200	\$ 400.00	\$ 360.00
5	1	Front Bumper Towing Cover	Damaged	\$ 38.00	\$ 34.20
6	1	Front Bumper Lower Garnish	Damaged	\$ 99.00	\$ 89.10
7	1	Front Fog Lamp Right with Garnish	Damaged	\$ 318.00	\$ 286.20
8	1	Front Headlamp right	Scratches 1523	\$ 1,830.00	\$ 1,647.00
9	1	Front Bonnet	Damaged 970.50	\$ 1,660.00	\$ 1,494.00
10	1	Front Bonnet Lock	Distorted	\$ 159.00	\$ 143.10
11	1	KIA Emblems	Necessary	\$ 55.00	\$ 49.50
12	1	Front Right Fender	Damaged	\$ 642.00	\$ 577.80
13	1	Front Reinforcement	Impacted	\$ 448.00	\$ 403.20
14	1	Front Top Panel Sample	Impacted	\$ 655.00	\$ 589.50
				<b>\$ 7,794.00</b>	<b>\$ 6,235.20</b>

Total (Parts): \$ 7,794.00 Less 20% \$ 6,235.20

3553.70  
20% - 2842.96

### Labour Charges

15	To fix & dismantle and remove damaged Frontal Portions; affected damaged portion.	\$ 1,000.00	600
16	To apply anti rust coat and affected areas	\$ -	
17	To check wiring	\$ 120.00	30
18	Welding and cutting of affected panels, including chassis alignment.	\$ 600.00	Xun
19	Spray painting for Frontal Portions affected parts	\$ 1,000.00	700
20	Refocusing of the front headlamp	\$ 180.00	30
21	Diagnose ECU system and reset error code.	\$ 120.00	-
22	3D Wheel Alignment	\$ -	1480
		<b>Total Labour:</b>	<b>\$ 3,020.00</b>

Total cost of repairs (Total cost of parts + Total Labour Cost) **\$ 9,255.20**

Less 20% **\$ 7,404.16**

4322.96

1/5 3450

04 days

SAT (SG) PTE LTD

Page 2 of 3

Taufik 97495749

- WP 3/2/21

1/5 Resurvey after repair

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: