



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM <i>liability check</i>	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	6 Battery Road #38-04 Singapore 049909
	Document Date 04/06/2021	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	10/04/2017	SLM7550Y	0	62566	69DS/SLM7550Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFB29F3702009389	2NRX142609	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: 04/06/2021 10. 30 HRTV VEH:SHD6402T ACC DATE:03/06/2021 TP INS:SMRT NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				122.40
4	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.				180.00
5	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIN ALL OTHER AFFECTED AREAS.				2160.00
6	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				1770.00
7	1	K81550-0D550 LAMP ASSY, RR COMBIN	1.00	319.70		319.70
8	2	K81560-0D550 LAMP ASSY, RR COMBIN	1.00	319.70		319.70
9	3	K81580-0D190 LAMP ASSY, RR, RH	1.00	189.30		189.30
10	4	K81590-0D150 LAMP ASSY, RR, LH	1.00	189.30		189.30
11	5	SPZ061-0D035 17 BACK SENSOR SILVER METALLIC	1.00	146.70		146.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			04/06/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	10/04/2017	SLM7550Y	0	62566	69DS/SLM7550Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFB29F3702009389	2NRX142609	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	6	K52159-0U908 COVER, RR BUMPER, L	1.00	521.00		521.00
13	7	K52161-0K040 PIECE, RR BUMPER	4.00	4.10		16.40
14	8	K52575-0D240 RETAINER, RR BUMPER	1.00	120.10		120.10
15	9	K52576-0D240 RETAINER, RR BUMPER	1.00	120.10		120.10
16	0	K52155-0D090 SUPPORT, RR BUMPER S	1.00	23.10		23.10
17	1	K52156-0D080 SUPPORT, RR BUMPER S	1.00	23.10		23.10
18	2	K52023-0D100 REINFORCEMENT SUB-AS	1.00	332.70		332.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			6,763.60
	Please acknowledge receipt of vehicle	Parts	2,321.20
		Labour	4,442.40
		Sublet	0.00
		Lubrication/Fluid	0.00
		Others	0.00
			GST 7.00% 473.45 Less 0.00 Amount Due 7,237.05

Company Copy