

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	-		R	ef:	CS/TP21006516/Kuce2	
	KARKAUNSL LEA		D	ate:	10/06/2021	
	1 SOON LEE STR #02-48 PIONEER	CENTRESINGAPORE 627605				
			С	ode:	TP2	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.		Veh. Inspected		WP0ZZZ98ZLS220111	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From		Assign Date		27/05/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	PORSCHE 718 BOXSTER GTS	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	WP0ZZZ98ZLS220111	Colour		METALLIC GREY	
	Odometer	-	Steering		JAMMED	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/35Z R20	PIRELLI		8 mm	
	L/H Front Tyre	235/35Z R20	PIRELLI		8 mm	
	R/H Rear Tyre	265/35Z R20	PIRELLI		8 mm	
	L/H Rear Tyre	265/35Z R20	PIRELLI		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date		Inspection Date		27/05/2021	
	Survey held at	KARKAUNSL LEASINGS PTE LTD				
		1 SOON LEE STREET, #02-47, PIONEER CENTRE, SINGAPORE 627605				
5a.		Re	emarks			

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.