

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBK 9135D
TP/MSIG

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES2190553/YISHUN

Date: 18 Jun 2021

Policy No: DMCVSNA00007812100

Veh Reg No: GBK9135D

Make/Model: TOYOTA TOYOTA
DYNA 150 5MT

Chassis No: JTFAT35Y50K216031

Engine No: 1KDB064725

Reg. Date: 15/01/2021

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 04/06/2021

TP Veh Reg No: YN3626E

Not Authorised
Acting B4 part
4 days
83376.95

Estimate Repair Cost to Vehicle No:GBK9135D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT LH DOOR 1650.40	1,794.20	1 PC	1,794.20	✓
2 FRONT LH DOOR TOP HINGE	110.00	1 PC	110.00	X
3 FRONT LH CORNAL GARNISH	336.30	1 PC	336.30	X
4 HEADLAMP LH 892.40	928.70	1 PC	928.70	X
5 FRONT LH SIDE MIRROR 600.10	600.10	1 PC	600.10	✓
			3,769.30	
	Less 25%		942.33	2,826.98
Special Net				
6 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	✓
7 FRONT LH DOOR ADVERTISEMENT STICKER	80.00	1 PC	80.00	60.00
			100.00	100.00
Labour				
8 REMOVE & REFIX FRT LH DOOR TRANSFER DOOR LOCK ASSY, INNER TRIM BOARD, RUBBER, REMOVE & REFIX FRT LH SIDE MIRROR & CORNAL GARNISH, KNOCK & REPAIR FRT LH W/SCREEN PILLAR & REALIGN CABIN POSITION	700.00	1 LA	700.00	400
9 REMOVE & REFIX FRT LH DOOR GLASS	60.00	1 LA	60.00	✓
10 PUTTY & RESPRAY ON FRT LH CORNAL GARNISH, FRT LH DOOR, PILLAR	500.00	1 LA	500.00	450
11 RUSTPROOFING	940	30.00	30.00	✓
			1,290.00	1,290.00

Total S\$ 4,216.98

Add GST @ 7% 295.19

Total Amount Payable S\$ 4,512.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

parts 2356.95
SN 80
Labour 940
=3376.95

AUTHORISED SIGNATURE