

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 07/06/2021

Estimated repair cost for vehicle no: SMR4775Y HONDA FIT 1.3GF CVT

CHASSIS: GK33433276 (2019)

07/06/2021

TP AXA.

Xiao Tony.

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Dented</i>	\$1,320.80	\$1,320.80 <i>475</i>
2	1	REAR BUMPER SIDE RETAINER LH <i>new</i>	\$85.20	<i>35</i> \$85.20
3	1	LH REAR FENDER <i>Dented</i>	\$1,654.40	\$1,654.40 <i>845</i>
4	1	LH REAR FENDER INNER SHIELD <i>new</i>	\$192.60	<i>x</i> \$192.60
5	1	LH REAR FEDNER QUARTER GLASS MOULDING <i>new</i>	\$169.10	<i>✓</i> \$169.10
6	1	LH REAR DOOR <i>Distorted</i>	\$1,479.90	\$1,479.90 <i>866</i>
7	1	LH REAR DOOR INNER TRIM BAORD <i>could</i>	\$1,427.60	\$1,427.60 <i>480</i>
8	2	LH REAR DOOR HINGE <i>new</i>	\$54.20	<i>x</i> \$108.40
9	1	LH REAR DOOR CHECKER	\$107.40	<i>+</i> \$107.40
10	1	LH REAR DOOR LOCK <i>Dented</i>	\$249.30	<i>✓</i> \$249.30
11	1	LH REAR DOOR REGULATOR GEAR <i>Dented</i>	\$421.70	<i>✓</i> \$421.70
12	1	LH REAR DOOR POWER WINDOW MOTOR <i>new</i>	\$639.30	<i>+</i> \$639.30
13	1	LH REAR DOOR LOCK CATCH <i>new</i>	\$43.20	<i>x</i> \$43.20
14	1	LH REAR WEATHER STRIPE <i>new</i>	\$183.20	<i>+</i> \$183.20
15	1	LH REAR DOOR GLASS INNER CHANNEL <i>new</i>	\$191.40	<i>+</i> \$191.40
16	1	REAR AXLE BEAM <i>Best.</i>	\$3,454.80	<i>✓</i> \$3,454.80 <i>855</i>
17	1	LH REAR SHOCK ABSORER <i>new</i>	\$459.20	<i>x</i> \$459.20
18	1	LH REAR WHEEL HUP BEARING <i>Dented</i>	\$131.50	<i>✓</i> \$131.50
19	1	LH REAR BRAKE ABS SENSOR <i>new</i>	\$427.20	<i>x</i> \$427.20
20	1	LH ROCKER PANEL OUTER PANEL <i>new</i>	\$847.60	<i>+</i> \$847.60
21	1	LH DOOR CENTER PILLAR OUTER PANEL <i>new</i>	\$976.38	<i>+</i> \$976.80
22	1	LH FRONT DOOR <i>Dented</i>	\$1,876.40	\$1,876.40 <i>985</i>
23	1	LH FRONT DOOR LOCK <i>Dented</i>	\$352.30	<i>✓</i> \$352.30
24	1	LH FRONT DOOR WEATHER STRIPE <i>new</i>	\$189.70	<i>+</i> \$189.70

6984 90

5587.92

TOTAL : \$16,989.00
 LESS 20 % \$3,397.80
 SUB-TOTAL : \$13,591.20

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	<i>30</i> \$80.00
2	1	LH REAR FENDER INNER SHIELD CLIPS <i>new</i>	\$60.00	<i>+</i> \$60.00
3	1	LH REAR FENDER SEALANT <i>new</i>	\$100.00	<i>50</i> \$100.00
4	1	LH REAR ROCKER PANEL SEALANT <i>new</i>	\$80.00	<i>+</i> \$80.00
5	1	LH DOOR CCENTER PILLAR SEALANT <i>new</i>	\$80.00	<i>+</i> \$80.00
6	1	BRAKE FLUIDE <i>new</i>	\$60.00	<i>+</i> \$60.00
7	1	LH REAR DOOR INNER TRIM BOARD CLIPS <i>new</i>	\$80.00	<i>30</i> \$80.00
8	1	BOTH LH DOOR STICKER <i>new</i>	\$450.00	<i>120</i> \$450.00
9	1	LH REAR QUARTER GLASS SEALANT <i>new</i>	\$80.00	<i>40</i> \$80.00
10	1	LH REAR SPORT RIM <i>old</i>	\$650.00	<i>400</i> \$650.00
11	1	LH REAR TYRE <i>new</i>	\$230.00	<i>+</i> \$230.00
12	1	LH FRONT DOOR AUDIO SOUND PROOF MAT <i>3 new</i>	\$450.00	<i>200</i> \$450.00
13	1	LH REAR DOOR AUDIO SOUND PROOF MAT <i>3 new</i>	\$450.00	<i>200</i> \$450.00

Door Advertisement Stickers x02
new

*400x2
= 800*

TOTAL: \$2,850.00

TOTAL PARTS : \$16,441.20

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & RENEW LH REAR UNDER CARRIAGE
- 6 LABOUR FOR TOP UP BRAKE FLUIDE & BLEED BRAKE SYSTEM
- 7 TO CONDUCT WHEEL ALIGNMENT
- 8 LABOUR FOR REMOVE & REFIX FUEL TANK
- 9 LABOUR FOR REMOVE & REFIX LH REAR QUARTER GLASS
- 10 LABOUR FOR REMOVE & TRANSFER BOTH LH DOORS FITTING
- 11 LABOUR FOR REMOVE & RENEW BOTH LH DOORS AUDIO SOUND PROOF MAT
- 12 LABOUR FOR REMOVE & REFIX LH UPHOLSTERY/ ROOF LINING
- 13 TO RESET & DIAGNOSE WARNING LIGHT ON

1000 \$2,000.00

1000 \$1,600.00

30 \$100.00

80 \$300.00

220 \$300.00

+ \$150.00

80 \$200.00

60 \$300.00

40 \$150.00

160 \$300.00

+ \$300.00

60 \$300.00

+ \$200.00

Subtotal :- \$6,200.00

Total:- \$22,641.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7.8K

total: 9787.92

L/s: 7.8K

Adrian L

L/s 10/06/21.

07 Days.