

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Toyota Camry (SBR173R)
Date of Loss	8 June 2021
Time of Loss	9:40
Loss Description	SHD9667B (INSD) TURNED OUT FROM MINOR ROAD HIT SBR173R (TP)
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	-\$30,351.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SBR173R

Registration State

SINGAPORE

Mileage

180538

Purchase Date

DD/MM/YYYY



Registration Date *

12/03/2008



Age of Vehicle

13

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2008

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

Lee Siew Kim

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Toyota	<input type="text" value="TOYOTA"/>
Model	Camry	<input type="text" value="CAMRY 2.0 AUTO ABS /"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MR053BK4107025258"/>
Engine No		<input type="text" value="1AZE088395"/>
Engine Capacity		<input type="text" value="1998"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

11/06/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

215/60R16

Front left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Spare wheel

Rear Tyre Size

215/60R16

Rear left side

YOKOHAMA6mm

Rear right side

YOKOHAMA6mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

25

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio












Parts & Labour



Miscellaneous

Summary

Parts

Add		Approve		Deny		Submit All							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT BUMPER	Deformed	0	565.1	No	0	25	0	0	423.83
	0	1		FRONT BUMPER CLIPS	Necessary	0	30	No	0	25	0	0	22.5
	0	1		FRONT BUMPER SIDE HOLDER RH	Cracked	0	54.9	No	0	25	0	0	41.18
	0	1		FRONT BUMPER SIDE HOLDER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER FOG LAMP RH	Cracked	0	298.8	No	0	25	0	0	224.1
	0	1		FRONT BUMPER FOG LAMP COVER RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER CHROME MOULDING RH	Cut	0	134.6	No	0	25	0	0	100.95

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT BUMPER REINFORCEMENT	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT GRILLE	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT GRILLE LOGO	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT GRILLE CLIPS	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT RH FENDER	Damaged	0	731.3	No	0	25	0	0	548.48
	0	1		FRONT RH FENDER INNER SHIELD	Deformed	0	201.5	No	0	25	0	0	151.13
	0	1		FRONT RH FENDER INNER SHIELD CLIPS	Necessary	0	30	No	0	25	0	0	22.5
	0	1		HEADLAMP RH	Cracked	0	1395	No	0	25	0	0	1046.25
	0	1		FRONT RH DOOR WING MIRROR	Repair	0	0	No	0	0	0	0	0
	0	1		FRONT RH LOWER ARM	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT RH KNUCKLE ARM	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT RH WHEEL HUB C/W BEARING	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT RH SHOCK ABSORBER	Serviceable	0	0	No	0	0	0	0	0











Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		PANEL BEATING	0	500	0	0	Reviewing		
	0		SPRAY PAINTING	0	500	0	0	Reviewing		
	0		WIRING	0	30	0	0	Reviewing		
	0		TO PERFORM WHEEL ALIGNMENT	0	80	0	0	Reviewing		
	0		TO DISMANTLE FRONT UNDERCARRIAGE	0	0	0	0	Deny		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition



Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 4 DAYS	Reviewing	0	0		
	0	FRONT RH WHEEL RIM	Reviewing	0	450	CUT	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FRONT RH TYRE	Deny	0	0	NOT NECESSARY	

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$4,140.92
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$2,580.92
Labour	\$0.00	\$1,110.00
Miscellaneous	\$0.00	\$450.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

3300





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$3,300.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$3,300.00

Submit for Review