

RS AUTO SERVICES

h.p 93825367

Not Notified
11 Sep 8300h
Recovery After Paint
4 days

Date : 14/06/2021

QUOTATION -THIRD PARTY CLAIM

FIRST CAPITAL INSURANCE LIMITED

15821EA

Attn: Motor Claim Department . Officer In Charge

Accident on : 21/05/2021

Claim : Third Party Claim
Veh. No : YQ 1839 E
Model : MIT CANTA FUSO
Insured Ins: NTUC INCOME

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : GBF 9706 H		
1	FRONT LH CORNER PANEL	\$ 618.00	X
1	FRONT TOP PANEL INNER	REPAIR	
1	FRONT TOP PANEL OUTER 382.15	\$ 480.00	✓
1	FRONT CENTER PANEL	REPAIR	
1	FUSO EMBLEM	\$ 120.00	X
1	FRONT GRILLE	\$ 1,185.00	X
1	HEADLAMP LH 535	\$ 980.00	✓
1	HEADLAMP PANEL LOWER RUBBER LH	\$ 650.00	X
1	HEADLAMP PANEL LH	\$ 295.00	X
1	SIGNAL LAMP LH 238	\$ 280.00	✓
1	HEADLAMP SIDE COVER LH	\$ 222.00	X
1	FRONT DOOR LH 1750	\$ 2,140.00	✓
1	FRONT DOOR LOWER HINGE LH	\$ 186.00	X
1	FRONT BUMPER CENTER	\$ 1,010.00	X
1	FRONT BUMPER RH SIDE 334	\$ 480.00	✓
1	FRONT BUMPER BRACKET LH	\$ 220.00	X
1	FRONT STEP GARNISH LH 409	\$ 718.00	✓
		\$ 9,584.00	
	Less 25%	\$ 1,916.80	
		\$ 7,667.20	
	TOTAL PARTS :	\$ 7,667.20	
QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 7,667.20	
	LABOUR CHARGE :		
	Labour charges	\$ 1,200.00	4501
	To do spray painting on accident affected area .	\$ 1,200.00	3501
	Transfer door parts to another door	\$ 120.00	601
	To do anti rust	\$ 90.00	301
	Check wiring ssystem, replace forcs headlamps	\$ 120.00	201
	Total Labour :	\$ 2,730.00	
	Total Parts & Labour :	\$ 10,397.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: