

3B EXPRESS AUTO PTE LTD

25 KAKI BUKIT ROAD 4, #06-77
TEL: 63416453/54, FAX: 63416450

INVOICE

TO: Islam Rabiul
12 Lorong 14 Geylang #01-11
Singapore 398048

DATE: 28-Jun-21

GBB 28763

S/NO.	Description		amount	Total
1	left side deck panel	damaged	720	66
2	air-con condenser	broken	445	66
3	air-con fan with motor	broken	198	00
4	air-con fan housing	broken	88	00
5	to dismantle, replace/cut, weld knock out dents to straighten areas affected by impacted as mentioned on the "parts Repair" column inclusive of replacement parts		\$950	1501 10% 1350.90 600
6	Putty & spray painting to adjusted panels. Job allowance. panel / materials		\$500	400.
7	apply rust proofing on adjusted panels		\$80	30
8	remove and rebuild labour		\$400	X nn.
				1030
	total adds up			\$3,290

Receiver Name: Islam Rabiul

NRIC: S 9615011C

Date: 28th DEC 2021

Tanpaku 97475749
-wp 16/6/21 @ 1pm
Resurvey after repair
Tanpaku @ lkkauto.com
4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2380.90
4/54/900 #
4 days.