

SMZ5052B OD AIG

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Tue 15/6/2021 6:34 AM

To: Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>

Cc: Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>

Dear Sir/Madam,

As instructed by our client , please proceed to repair the **insured vehicle SMZ5052B (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Re-inspection require on hidden part, check item, supplementary part with clear photo

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)