

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Not Authorised
11 Days @ 23,500/-
Putting After Paint

Estimate : TP21/020

Date : 15/06/2021
Vehicle Num. : SCV 5225J
Make/Model : MERCEDES E250-2015
Chassis/Eng# : WDD2120362B122957/2749203034751
Accident Date : 10/06/2021
Claim No. :
Reference : LYB/SCV5225J/AIG/tp
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		NETT ITEMS :		
1	1	FRONT BONNET	2645	
2	1	FRONT BONNET SEAL (CENTRE)		
3	1	FRONT BONNET INSULATOR		
4	10	FRONT BONNET INSULATOR CLIPS		
5	2	FRONT BONNET HINGES		
6	2	FRONT BONNET SPRING		
7	1	FRONT BONNET EMBLEM		
8	2	FRONT BONNET LOCK TOP LH & RH		
9	2	FRONT BONNET LOCK BOTTOM LH & RH		
10	1	FRONT BONNET LOCK CENTRE		
11	1	FRONT BONNET LOCK SWITCH		
12	1	FRONT BUMPER		
13	1	FRONT BUMPER GRILLE SUPPORT		
14	2	FRONT BUMPER SIDE RETAINER		
15	1	FRONT BUMPER REINFORCEMENT		
16	1	FRONT BUMPER BEAM		
17	1	FRONT BUMPER LOWER GRILLE/CENTRE		
18	2	FRONT BUMPER LOWER GRILLE/SIDE		
19	2	FRONT BUMPER LOWER GRILLE CHROME/ SIDE		
20	1	FRONT BUMPER TOWING HOOK COVER		
21	2	FRONT HEADLAMP ASSY @ 5520		
22	2	FRONT HEADLAMP LOWER PANEL		
23	1	FRONT FENDER/RH		
24	1	FRONT AIR CON CONDENSER		

CM	2,989.00	✓
CM	128.00	✓
CM	215.00	X
4.50	45.00	✓
178.00	356.00	X
16.00	32.00	X
	111.00	✓
39.00	78.00	✓
41.00	82.00	✓
	98.00	✓
	49.00	✓
Bu	1,658.00	✓
pi	115.00	✓
98.00	192.00	X
	648.00	✓
	300.00	X
	88.00	X
57.00	114.00	X
120.00	240.00	X
	61.00	X
my CM	5,878.00	11,756.00
	313.00	626.00
		1,214.00
		1,513.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (Subsidiary) Survey

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
CHARTIS BUILDING SINGAPORE 079120


Attention : Motor Claim Department
Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP21/020

Date : 15/06/2021
Vehicle Num. : SCV 5225J
Make/Model : MERCEDES E250-2015
Chassis/Eng# : WDD2120362B122957/27492030347587
Accident Date : 10/06/2021
Claim No. :
Reference : LYB/SCV5225J/AIG/tp
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	FRONT AIR CON HOSE	210.00	X
26.	1	FRONT INTAKE HOSE	258.00	2
27.	1	FRONT RADIATOR 1486	1,598.00	2
28.	1	FRONT RADIATOR UPPER BRAFFLE	49.00	2
29.	1	FRONT RADIATOR FAN ASSY 1581	1,742.00	2
30.	1	FRONT RADIATOR GRILLE CARRIER	298.00	—
31.	1	FRONT RADIATOR GRILLE BASE	220.00	—
32.	1	FRONT RADIATOR GRILLE TRIM/ CHROME	403.00	—
33.	1	FRONT RADIATOR GRILLE COVER	208.00	—
34.	4	FRONT RADIATOR GRILLE MLDG	192.00	—
35.	1	FRONT RADIATOR GRILLE STAR	155.00	—
36.	1	FRONT RADIATOR GRILLE STAR BASE	88.00	—
37.	1	FRONT SUPPORT TOP PANEL/ CENTRE	185.00	—
38.	1	FRONT SUPPORT TOP PANEL/LH	317.00	2
39.	1	FRONT SUPPORT TOP PANEL/RH	317.00	2
40.	1	FRONT SUPPORT TOP CENTRE GARNISH	153.00	—
41.	1	FRONT SUPPORT BRACE PANEL	85.00	2
42.	1	FRONT SENSOR	313.00	SVC 1,252.00 7+
43.	4	FRONT SENSOR HOLDERS	26.00	na 104.00 X
44.	1	FRONT SENSOR WIRE HARNESS	268.00	X
45.	1	ROOF PANEL SIDE MLDG	455.00	X
46.	8	ROOF PANEL SIDE MLDG CLIPS	44.00	X
47.	1	REAR BOOT LID	3,312.00	—
48.	1	REAR BOOT LID WEATHERSTRIP	217.00	X
49.	1	REAR BOOT LID STAR EMBLEM	65.00	—
50.	3	REAR BOOT LID STAR CLIPS	2.00	na 6.00 —

CONTINUE / ...



LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department
Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP21/020

Date : 15/06/2021
Vehicle Num. : SCV 5225J
Make/Model : MERCEDES E250-2015
Chassis/Eng# : WDD2120362B122957/27492030347587
Accident Date : 10/06/2021
Claim No. :
Reference : LYB/SCV5225J/AIG/tp
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
51	1	REAR EMBLEM 'E250'		91.00
52	1	REAR EMBLEM '7G-TRONIC'		111.00
53	1	REAR LID OUTER HANDLE (CHROME)		134.00
54	5	REAR LID OUTER HANDLE INSIDE CLIP	3.50	17.50
55	1	REAR BUMPER		1,859.00
56	2	REAR BUMPER RETAINER	39.00	78.00
57	1	REAR BUMPER BEAM		969.00
58	1	REAR BUMPER INSIDE PART		297.00
59	2	REAR BUMPER BRACKET	27.00	54.00
60	2	REAR BUMPER CHROME (SIDE)	152.00	304.00
61	1	REAR BUMPER LOWER CHROME		189.00
62	4	REAR REVERSE PDC SENSOR	313.00	1,252.00
63	1	REAR REVERSE PDC SENSOR HOLDER	nec 28.00	104.00
64	1	REAR SILENCER OUTER CHROME FINISHER		285.00
65	1	REAR SILENCER OUTER CHROME FINISHER BRACKET		53.00
66	1	REAR SILENCER HEAT SHIELD		102.00
67	1	REAR FENDER/ RH		2,655.00
68	1	REAR FENDER INNER SHIELD/ RH		282.00
69	1	REAR TALLAMP/ RH		864.00
70	1	REAR REFLECTOR/ RH		538.00
Nett Total S\$:				45,147.50
10.00% Discount S\$:				4,514.75
				40,632.75

SPECIAL NETT ITEMS :
FRONT NO PLATE (EMBOSS)

Net 25.00



LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
CHARTIS BUILDING SINGAPORE 079120

Estimate : TP21/020

Date : 15/06/2021
Vehicle Num. : SCV 5225J
Make/Model : MERCEDES E250-2015
Chassis/Eng# : WDD2120362B122957/27492030347587
Accident Date : 10/06/2021
Claim No. :
Reference : LYB/SCV5225J/AIG/tp
Policy No. :

Attention : Motor Claim Department
Contact : 64191000 Fax No. : 64193727 Claims Dept

S/N	Quantity	Particular	Unit Price	Amount S\$
2	1	FRONT NO. PLATE HOLDER		
3	20	FRONT BUMPER EXTENSION FASTENER		25.00 X
4	20	FRONT BUMPER EXTENSION GROMMET SCREW	7.00	140.00
5	20	FRONT BUMPER FASTENER	8.00	160.00
	30	RIVETS 003 990 9497MB	8.00	160.00
			5.00	150.00
		Special Nett Total S\$:		650.00
		LABOUR :		
		MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB	nn	400.00 X
		TO RE-SET ABS SYSTEM & EARSE REGISTERED FAULT	nn	180.00 X
		TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION		55.00 2ol
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED FRT PANELS		120.00 6ol
		LABOUR CHARGE FOR DISMANTLE & RENEW AIR-CON CONDENSER, HOSE & AIR CON RELATED PARTS		280.00 100ol
		TO VACUM AND TOP UP GAS		180.00
		LABOUR TO CHECK AND REPLACE FRONT SENSOR		120.00 6ol
		TO REPAIR, PANEL BEAT ON AFECTED AREA, RE-STRAIGHTEN ON AFFECTED RIGHT FRT HOUSING, CUT & WELD ON REPLACED PANEL		

YEW BOO SPRAY PAINT CO.

SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Bus. Reg. No. : 200514/00L

ASIA PACIFIC INSURANCE PTE LTD
 SHENTON WAY #07-16
 ARTIS BUILDING SINGAPORE 079120

Motor Claim Department
 Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP21/020

Date : 15/06/2021
 Vehicle Num. : SCV 5225J
 Make/Model : MERCEDES E250-2015
 Chassis/Eng# : WDD2120362B122957/27492030347587
 Accident Date : 10/06/2021
 Claim No. :
 Reference : LYB/SCV5225J/AIG/tp
 Policy No. :

Quantity	Particular	Unit Price	Amount S\$
	& LABOUR TO REPLACE THE ABOVE FRONT PARTS		2,000.00 800/
	TO PUTTY, PRIMER & SPRAY PAINT ON FRT BONNET, FRT BUMPER, RIGHT & LEFT FRT FENDER, LEFT & RIGHT AFFECTED ROOF TOP SIDE CHANNEL & FRONT SENSOR USING 2K PAINT		2,100.00 1800/
	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED REAR PANEL		120.00 30/
	LABOUR TO REMOVE/REFIX REAR SEAT, INTERIOR GARNISH, ETC		220.00 80/
	LABOUR TO REMOVE & REFIX REAR WINDSCREEN IN ORDER TO FACILITATE REPAIR JOBS	nn	150.00 X
	LABOUR TO CHECK AND REPLACE REAR SENSOR		120.00 60/
	TO REMOVE, REPAIR REAR EXHAUST SILENCER & REPLACE HEAT SHIELD & REAR SILENCER OUTER CHROME PIPE		150.00 60/
	TO CHECK REAR WIRING HARNESS & FUNCTION		120.00 20/
	TO REPAIR, PANEL BEAT ON REAR AFFECTED AREA, CUT & WELD ON REPLACED PANEL, RE-STRAIGHTEN ON REAR AFFECTED AREA & LABOUR TO REPLACE THE ABOVE PARTS		2,000.00 800/
	TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, REAR AFFECTED LEFT & RIGHT		

CONTINUE /

LIM YEW BOO SPRAY PAINT CO.

Page 6 / 6

SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
Email : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
S.S. Reg. No. : 200514/00L

ASIA PACIFIC INSURANCE PTE LTD
HENTON WAY #07-16
RTIS BUILDING SINGAPORE 079120

Motor Claim Department
Tel : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP21/020

Date : 15/06/2021
Vehicle Num. : SCV 5225J
Make/Model : MERCEDES E250-2015
Chassis/Eng# : WDD2120362B122957/27492030347587
Accident Date : 10/06/2021
Claim No. :
Reference : LYB/SCV5225J/AIG/tp
Policy No. :

Quantity	Particular	Unit Price	Amount S\$
	FENDER, REAR REVERSE SENSOR USING 2K PAINT		1,800.00
	Labour Total S\$:		10,115.00

8841

E. & O.E.

Total S\$: 51,407.75
=====



LIM YEW BOO SPRAY PAINT CO.