

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD	_	Ref:	CS3/INC19018821/Gud3e2-1	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	14/06/2021	
	ATTN: JENNY PE			Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	YN 8530D	Veh. Inspected		FBH 5371E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1067552-002	Excess (\$)		0.00	
	Assign From	JENNY PE	Assign Date		21/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA FZ16ST	c.c		153	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	ME145S0B5D2008836	Colour		RED	
	Odometer	49801 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/80 R17	PIRELLI		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70 R17	PIRELLI		5 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	18/10/2019	Inspection Date)	23/10/2019	
	Survey held at	53 UBI AVE 1 #01-23				
	Repairer	KARZ WORK SOLUTIONS				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					