

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref: CS3/LPC21004585/Etf3e2-1		
300 BEACH ROAD		Date: 21/06/2021		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGJ 4148X	Veh. Inspected	SKG 7552K	
Policy No.	Z20VP05027011	Coverage (\$)	0.00	
Claim No.	20/21/21/VP05/024434	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	15/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ACR507059302	Colour	BEIGE	
Odometer	191842 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55Z R17	HEADKING	5 mm	
L/H Front Tyre	225/55Z R17	HEADKING	5 mm	
R/H Rear Tyre	225/55Z R17	HEADKING	5 mm	
L/H Rear Tyre	225/55Z R17	HEADKING	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2021	Inspection Date	13/04/2021	
Survey held at	GALAXY AUTO CARE PTE LTD 13 KAKI BUKIT ROAD 4 #01-23 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		