

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KOH TAIWEI JOHN
 75 ANCHORVALE CRESCENT #10-11
 SINGAPORE 544662

Estimate No: MC1901991
 Date: 14 Jun 2021
 Policy No: P10527363R00
 Veh Reg No: **SMJ8636G**
 Make/Model: HONDA FIT HYBRID 1.5
 AUTO

ATTN:

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 13/06/2021
 TP Veh Reg No: SKU4760Y

Estimate Repair Cost to Vehicle No :SMJ8636G

2019

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT FENDER RH	1 PC	✓ 368.50 DDV	
2 FRONT FENDER LOGO "HYBRID"	1 PC	✓ 58.00 NECV	
3 FRONT FENDER COWLING RH	1 PC	75.00 91.50 BRV	
4 FRONT FENDER COWLING CLIP	8 PC	20.00 ✓ 28.00 NECV	
5 FRONT FENDER STAND GARNISH RH -CHECK PRICE	1 PC	0.00 ? NDX	
6 FRONT DOOR RH	1 PC	✓ 757.20 DDV	
7 FRONT DOOR RH STICKER SET	1 PC	25.00 ✓ 35.80 NECV	
8 FRONT DOOR RH HINGE BOTTOM	1 PC	48.60 NDX	
9 FRONT DOOR RH CHECK	1 PC	48.60 NDX	
10 FRONT DOOR RH RUBBER FRONT	1 PC	44.30 NDX	
11 FRONT DOOR RH RUBBER BOTTOM	1 PC	18.50 NDX	
12 FRONT DOOR RH WINDOW GLASS	1 PC	417.20 NDX	
13 FRONT DOOR RH WINDOW GEAR WITH MOTOR	1 PC	416.50 NDX	
14 REAR DOOR RH	1 PC	736.20 799.50 DDV	
15 REAR DOOR RH STICKER	1 PC	✓ 25.00 NECV	
16 REAR DOOR RH HINGE BOTTOM	1 PC	32.70 NDX	
17 REAR DOOR RH CHECK	1 PC	40.50 NDX	
18 REAR DOOR RH RUBBER FRONT	1 PC	46.80 NDX	
19 REAR DOOR RH RUBBER REAR	1 PC	19.50 NDX	
20 REAR DOOR RH RUBBER BOTTOM	1 PC	15.40 NDX	
21 REAR BUMPER	1 PC	529.90 CUT X	
22 REAR BUMPER SIDE RETAINER RH	1 PC	✓ 18.70 NECV	
23 REAR BUMPER CLIP	12 PC	30.00 42.00 NECV	
24 FRONT WHEEL HUB RH	1 PC	NDX 138.20	
25 FRONT WHEEL BEARING RH	1 PC	Nec ✓ 168.00 ? NDX	
26 REAR WHEEL HUB AND BEARING RH	1 PC	ND X 306.60	
27 FRONT DOOR RH LOCK	1 PC	ND X 262.30	
28 REAR DOOR RH LOCK	1 PC	ND X 210.00	

2132.40

426.48

Less 20%

4,957.80

991.56

3,966.24

Special Nett

- 29 SPORT RIM - RH & RHR -CHECK PRICE
 30 TYRE - RH & RHR -CHECK PRICE

local repair 1 pc 200.00 0.0000
 2 PC 0.0000

ND X

0.00

0.00

LABOUR

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : KOH TAIWEI JOHN
 75 ANCHORVALE CRESCENT #10-11

SINGAPORE 544662

ATTN:

Estimate No: MC1901991
 Date: 14 Jun 2021
 Policy No: P10527363R00
 Veh Reg No: SMJ8636G
 Make/Model: HONDA FIT HYBRID 1.5
 AUTO

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 13/06/2021
 TP Veh Reg No: SKU4760Y

Estimate Repair Cost to Vehicle No :SMJ8636G

Description	Quantity	List Price	Amount
		S\$	S\$
31 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	80.00 X N/A
32 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR. RHF & RHR	2 PC	80.00 240.00	240.00 ✓
33 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS. RH	1 PC	180.00	N/A
34 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. RHF & RHR	1 PC	180.00	N/A 80
35 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	X 60.00	✓ nn
36 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	N/A
37 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR ROCKER PANEL RH, CENTRE PILLAR RH, REAR FENDER RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00 1,000.00	1,000.00 ✓
38 TO SPRAY FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE PILLAR RH, REAR FENDER RH, REAR BUMPER	1 PC	1,000.00	1,200.00 ✓
		3,020.00	3,020.00
		Total	S\$ 6,986.24
		Add GST @ 7%	489.04
		Total Amount Payable	S\$ 7,475.28

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED SEVENTY FIVE AND CENTS TWENTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

AKK Auto Consultants hence notify the Repairer of the following:

To survey vehicle after survey period

To display damaged part(s) during survey

Part prices are subject to confirmation

Add GST @ 7%

Third party survey is on a "Time and Materials" basis

Total Amount Payable

is subject to final approval from Insurance Company

19/06/2021

Signature: _____

Date: _____

For AH LIM MOTOR COMPANY

Part by Part repair
 Repair days 6



AUTHORIZED SIGNATURE

Part 1705.92
 SH 200.00
 Labour 1740.00
 3645.92

~~GR 2645.00~~

TGlim Min 3/9/2021

Before paint
 Resurvey
 16/6/2021 29/6/2021
 1334 1257
 TGlim Min TGlim
 97365577 TGlim