



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH			Ref: CC4/ASM21006706/Kpa3q2 Date: 07/07/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 3815K	Veh. Inspected	GBD 4405U
	Policy No.	P2070742	Coverage (\$)	0.00
	Claim No.	S1M03BAE	Excess (\$)	0.00
	Assign From		Assign Date	15/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	KYD2318016581	Colour	SILVER
	Odometer	307053 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195R15X8	OHTSU	9 mm
	L/H Front Tyre	195R15X8	OHTSU	9 mm
	R/H Rear Tyre	155 R12X8 (D)	FALKEN	9/9 mm
	L/H Rear Tyre	155 R12X8 (D)	FALKEN	9/9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/06/2021	Inspection Date	17/06/2021
	Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	