



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG21006711/Tqy3	
			Date: 15/06/2021	
			Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMM 7879M	Veh. Inspected	FBQ 5515K
	Policy No.	1001437475	Coverage (\$)	0.00
	Claim No.	258313	Excess (\$)	0.00
	Assign From	MERIMEN (KOH MING SHAO)	Assign Date	15/06/2021
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH3UG0740K0153242	Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	03/06/2021	Inspection Date	15/06/2021
	Survey held at	25Kaki Bukit Road 4 #01-25 Synergy @ KB		
	Repairer	UNITED CYCLES LLP		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			