



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref:	CS3/ASM21001336/T1ps3q2-1
8 SHENTON WAY #24-01			Date:	05/11/2021
AXA TOWERSINGAPORE 068811				
ATTN:CHAN KIAN CHUAN			Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6645J	Veh. Inspected	SMQ 6846T
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03597	Excess (\$)	0.00
	Assign From		Assign Date	28/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 316	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBA3A12090J719817	Colour	WHITE
	Odometer	126898 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/30 R19	FALKEN	6 mm
	L/H Front Tyre	275/30 R19	FALKEN	6 mm
	R/H Rear Tyre	275/30 R19	FALKEN	6 mm
	L/H Rear Tyre	275/30 R19	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/01/2021	Inspection Date	28/01/2021
	Survey held at	AKA AUTO PTE LTD		
		25 KAKI BUKIT ROAD 4, #05-36, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	