

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AIG

Owner : Muhammad Nur Haikl Diny Al-
Faez Bin Fitri

Accident Date : 10-Jun-21

Vehicle No : FY6946D

TP AIG.
Xiao Tony

Vehicle Model : Piaggio Vespa
PX150

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender <i>Distorted</i>	\$ 145.00 ✓
1	Front fork assy <i>? SVC</i>	\$ 950.00 <i>+</i>
1	Front shock absorber <i>Best</i>	\$ 680.00 <i>300</i>
1	Front fork cover <i>2nd</i>	\$ 85.00 ✓
1	Front rim <i>new</i>	\$ 180.00 <i>+</i>
1	Front brake disc <i>new</i>	\$ 220.00 <i>+</i>
1	Top cowling <i>new</i>	\$ 165.00 ✓
1	Front centre cowling <i>Distorted</i>	\$ 180.00 ✓
1	Front panel moulding <i>at</i>	\$ 160.00 ✓
1	Front living moulding <i>new</i>	\$ 180.00 <i>+</i>
1	Headlamp <i>new</i>	\$ 180.00 ✓
1	Meter assy <i>new</i>	\$ 480.00 <i>+</i>
1	Front signals (1 set) <i>new</i>	\$ 170.00 ✓
1	Side mirrors (1 set) <i>Missing</i>	\$ 160.00 ✓
1	Handle-bar <i>Best</i>	\$ 235.00 ✓
1	Hand grip (1 set) <i>new</i>	\$ 65.00 <i>+</i>
1	Brake lever <i>at</i>	\$ 450.00 <i>45</i>
2	Engine cover <i>Best</i>	\$ 65.00 <i>250</i>
2	Engine cover moulding <i>at</i>	\$ 250.00 <i>65</i>
1	Kick starter <i>at</i>	\$ 130.00 ✓
1	Gear selector <i>2nd</i>	\$ 150.00 <i>2</i>
1	Rear signals (1 set) <i>new</i>	\$ 160.00 ✓
1	Rear shock absorber <i>Best</i>	\$ 680.00 <i>220</i>
1	Rear taillamp <i>new</i>	\$ 135.00 ✓
		\$ 6,255.00
	Less 10%	\$ 625.50
		\$ 5,629.50

3015
2713.50

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Muhammad Nur Haikl Diny Al-
Faez Bin Fitri

Accident Date : 10-Jun-21


Vehicle No : FY6946D

Vehicle Model : Piaggio Vespa
PX150

Estimated Repair Costs

<u>Special Net Items</u>			
1	Number plate (1 set) <i>replaced</i>	\$	28.00 ✓
1	Steering cone (1 set) <i>new</i>	\$	96.00 ✓
1	"VESPA" emblem <i>new</i>	\$	100.00 <i>60</i>
		\$	224.00
<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service (LOD)	\$	50.00 ✓
2	To check wiring and reset headlamp focusing	\$	80.00 <i>50</i>
3	To provide spray paint work	\$	1,200.00 <i>300</i>
4	To repair body frame	\$	450.00 <i>300</i>
5	To provide labour	\$	480.00 <i>380</i>
		\$	2,260.00
Grand Total		\$	8,113.50

Singapore Dollars: Eight Thousand One Hundred Thirteen and Cents: Fifty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/S 16/06/21
09 Days
Whl: 41775
H/S: 3.3K
(with Vespa)