GBK 3403U

<u>PARTS</u>				<u>S/N</u>		<u>LABOUR</u>		SUPP (PARTS)		
	\$891.20	\$0.00	\$0.00		\$30.00		\$1,500.00		\$0.00	
	\$122.50	\$0.00	\$0.00		\$50.00		\$20.00		\$0.00	
	\$1,715.10	\$0.00	\$0.00		\$100.00		\$60.00		\$0.00	
	\$132.70	\$0.00	\$0.00		\$100.00		\$60.00		\$0.00	
	\$305.10	\$0.00	\$0.00		\$0.00		\$100.00		\$0.00	
	\$305.10	\$0.00	\$0.00		\$0.00		\$1,000.00		\$0.00	
	\$286.20	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$215.40	\$0.00	\$0.00		\$0.00		\$0.00			
	\$261.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$284.10	\$0.00	\$0.00		\$0.00		\$0.00		0%	
	\$282.60	\$0.00	\$0.00		\$0.00		\$0.00		<u>\$0.00</u>	
	\$312.00	\$0.00	\$0.00		\$0.00		\$0.00	SUPP (SN)		
	\$879.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00	
	\$0.00	\$0.00	\$0.00		<u>\$280.00</u>		\$2,740.00		<u>\$0.00</u>	
	\$0.00	\$0.00	\$0.00			-				
	\$0.00	\$0.00	\$0.00					SUPP(LABOUR)		
	\$0.00	\$0.00	\$0.00			TOTAL			\$0.00	
	\$0.00	\$0.00	\$0.00				\$2,996.00		\$0.00	
	\$0.00	\$0.00	\$0.00				\$280.00		\$0.00	
	\$0.00	\$0.00	\$0.00				\$2,740.00		<u>\$0.00</u>	
	\$0.00	\$0.00	\$0.00			SUPP	\$0.00		_	
	\$0.00	\$0.00	\$0.00			P/P	\$6,016.00	MAKE / MODEL	TOYOTA HIACE (2982cc)	
	\$0.00	\$0.00	\$0.00				\$0.00	MARKET VALUE	\$72,000.00	
	\$0.00	\$0.00	\$0.00				0%	LTA REBATE	\$18,705.00	
	\$0.00	\$0.00	\$5,992.00				\$0.00	NETT VALUE	\$53,295.00	
	\$0.00	\$0.00				L/S	\$6,000.00	RED	\$10,127.10	63%
_	\$0.00	\$0.00	\$5,992.00					TOTAL TP EST	\$16,127.10	
	\$0.00	\$0.00	50%					REPAIR DAYS	<u>6</u>	
	\$0.00		\$2,996.00							