MFORTDELGRO ENGINEERING PTE LTD

KEPAIR ESTIMATE*

VEHICLE NO

SHD4357D

MAKE

: HYUNDAI

14. June 2021 DATE:

ODEL	IONIQ		DOA	14. Jun. 2021	<u>NTUC</u>	_
Qty	Parts D	escription/ Labour	Type	Unit Price	Amount	
	1 FRT BUMPER ASSY				\$430.9 6	ar-
10	REAR BUMPER CLIP	S			\$22.00	ا بق
	1 FRT BUMPER BRACKET LH				\$35.00	X
	1 FRT FENDER LH			•	588.8	16
i.	FRT FENDER EMBLE	M LH	1	1	\$26.60	ng
					\$1,103.35	
					, ,	
		SUB TOTAL		1068.30	\$1,103.35	1
		LESS 20%		4	\$220.67	ı
		DISCOUNTED TOTAL	1	854.64	\$882.68	1
		DISCOUNTED TOTAL	1		3882.08	
	Í		i		1	
			4	i .		Ne
						Ne
	*					
	lahan Chama	IVVA		,		
	Labour Charge	LKK Auto Consultants hence no the Repairer of the following:	ify			l
	PANEL BEATING	TO COULVEY DESCRIPTION CONTRACTOR		350	\$800.00	
	SPRAY PAINT	• 10 display damaged parties during	la la	350	\$600.00	
ľ	WIRING	Parts prices are subject to confirmation Third party survey is on a "Without Pre" No illegal modification(s) is a transfer.		850 nn.	≭ \$50.00	
1						
		 Supplementary item(s) must be resurve is subject to final approval from Insuran 	yed and			
1		Astronom insuran	ce Company			
Î		Acknowledged by Repairer Signature:				
		Date:				
		¥		41704.64	XXX	
		" TOTAL LABOUR		(1)		
		- STAL PUROUK		41704.64 *2days	\$1,450.00	
		FSTIMATE TOTAL		11 0		
		ESTIMATE TOTAL			\$2,332.68	
Į ir	nis is an initial estimate b	rased on a visual inspection of the	above veh	icle. The final repair a	(antion of the	
be	e prepared after the vehi	cle is surveyed by a motor Survey	Or appoint	ed by the in-	iontum Will	

Tauffer 97475749

WP 15/6/21 Q 4 pm.

pp Resur helpre part

farfter @ Chlantow m.

2 deys