

Our Job Ref No : 305473281Date 22/06/21ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr TAUFIKHVehicle Reg No. SHC3465LDate of Accident : 11/06/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FF 6006S

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$8,265.10 8265.17

(b) Labour Charges


\$1,740.00**Total for Part-By-Part Repair Cost**\$10,005.10 \$10,005.17

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%**Final Lumpsum Repair cost**3. Estimated normal period for repairs: 4 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : JUMANITel : 62148315Fax : 65468156Signature : Name : TaufikhDate : 9/7/21**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

VEHICLE NO. : SHC3465L

TYPE OF CASE : NTUC

JOB CARD NO. 305473281

SURVEY BY : LKK-TAUFIKH

ACC.DATE 11/06/21

DATE :

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	REMARKS
BONNET INSULATOR CLIPS	9	\$2.30	LIST NEC ✓
CLIP PIN HOLD	4	\$2.30	LIST NEC ✓
FRT FENDER RETAINER	4	\$16.80	LIST NEC ✓
BRACKET FRT SIDE PANEL LH	1	56.10	Bt
CHECK ITEMS.			
FRT BUMPER SIDE MLDG LH		\$172.50	de ✓
FRT LOWER BALL JOINT LH		\$199.98	bt ✓
FRT TIE ROD LH		\$159.30	bt ✓
FRT HUB ASSY LH		\$549.70	bt ✓
FRT FENDER EXTENSION LH		\$47.20	bt ✓
FRT FENDER BRACKET LH		\$82.30	bt ✓
LABOUR			
TOTAL:		\$1,232.38	JUMANI

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.06.2021

Time: 11:52:56

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305473281
 REGN NO : SHC3465L
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4A)
 DATE OF REGN : 04.12.2019
 DATE/TIME IN : 11.06.2021 23:20
 ACCIDENT DATE : 11.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2685-G	MOULDING FRONT BUMPER SID	1	172.50	25.00	129.37	
0002	04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID	1	26.60	25.00	19.95	
0003	04-01-0302-2871-G	SUPPORT FRONT BUMPER SIDE	1	82.30	25.00	61.72	
0004	04-01-0302-2877-G	BRACKET FRT SIDE PANEL LH	1	56.10	25.00	42.07	bt ✓
0005	04-01-0302-2879-G	EXTENSION FRT FENDER LH	1	47.20	25.00	35.40	
0006	04-01-0302-0574-A	FENDER SUB-ASSY FRONT LH+	1	945.30	25.00	708.97	
0007	04-01-0302-2834-G	LINER FRONT FENDER LH^	1	198.50	25.00	148.87	
0008	04-01-0302-2746-G	UNIT HEADLAMP LH	1	3,455.00	25.00	2,591.25	
0009	04-01-0302-0572-A	HOOD SUB-ASSY+	1	950.50	25.00	712.87	
0010	04-01-0302-2278-G	FRT BUMPER CLIPS	10	22.00	25.00	16.50	
0011	04-01-0302-2353-G	CLIP HOOD INSULATOR	9	20.70	25.00	15.52	nec ✓
0012	04-01-0302-2872-A	HINGE ASSY HOOD LH	1	87.70	25.00	65.77	
0013	04-01-0302-2972-A	HINGE ASSY HOOD RH	1	87.70	25.00	65.77	

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305473281
REGN NO	:	SHC3465L
MILEAGE	:	0000000000
MAKE	:	TOYOTA
MODEL	:	PRIUS HYBRID
DATE OF REGN	:	04.12.2019
DATE/TIME IN	:	11.06.2021 23:2
ACCIDENT DATE	:	11.06.2021

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT					
0014	04-01-0302-2534-G	COVER FRONT BUMPER	1	499.90	25.00	374.92	
0015	04-01-0302-2355-G	CLIP PIN HOLD	4	5.20	25.00	3.90	nec ✓
0016	04-01-0302-2354-G	RETAINER FRONT FENDER LIN	4	67.20	25.00	50.40	nec ✓
0017	03-01-0302-2020-G	WHEEL DISC+	1	1,570.55	25.00	1,177.91	
0018	03-01-0302-2802-G	LOWER ARM SUB-ASSY LH+	1	637.50	25.00	478.12	
0019	03-01-0302-2804-G	ABSORBER ASSY SHOCK FRT L	1	401.80	25.00	301.35	
0020	03-01-0302-0142-G	HUB SUB-ASSY FRT AXLE RH/	1	549.70	25.00	412.27	
0021	03-01-0302-2800-G	END SUB-ASSY TIE ROD LH+	1	159.30	25.00	119.47	
0022	03-01-0302-0119-G	JOINT ASSY LOWER BALL FRT	1	199.98	25.00	149.98	
0023	03-01-0302-2070-G	ABSORBER ASSY MLDG FRT/LH	1	196.20	25.00	147.15	
0024	03-01-0302-0139-G	KNUCKLE STEERING LH^	1	580.80	25.00	435.60	11020.23
							8265.17
						SUB-TOTAL	: 8,265.10

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305473281
REGN NO : SHC3465L
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 04.12.2019
DATE/TIME IN : 11.06.2021 23:2
ACCIDENT DATE : 11.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

JOB NATURE

0000 PB	PANEL BEATING	700.00	
0001 SP	SPRAYPAINT CHARGE	750.00	
0002 17-01	CHECK ALL LIGHTING	30.00	
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00	
0004 20-12	REMOVE/REFIX FRT SUSPENSION ASST REPA	150.00	
0005 20-08	ADJUST FOUR WHEEL ALIGNMENT	80.00	
		SUB-TOTAL	: 1,740.00
			10,005.17
		TOTAL	: 10,005.10

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :