



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21006747/Atf3n2	
			Date: 31/08/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 5493Y	Veh. Inspected	YQ 2493L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101804/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	16/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi canter	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	FEB21EA35129	Colour	WHITE
	Odometer	15278 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	DUNLOP	6 mm
	L/H Front Tyre	195 R15	DUNLOP	6 mm
	R/H Rear Tyre	195 R15	DUNLOP	6 mm
	L/H Rear Tyre	195 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/06/2021	Inspection Date	18/06/2021
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	