

































Report No: 0544-19-TCA

16 December 2019

ACCIDENT VEHICLE SURVEY REPORT

Koh Contracts & Services Pte Ltd
80 Genting Lane #01-01 Ruby Industrial Complex
Singapore 349565

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	GBF7473S	<i>Odometer:</i>	50836km
<i>Make & Model:</i>	Nissan Cabstar 3.0	<i>Colour:</i>	Gold
<i>Chassis number:</i>	JN1SC2F24Z0859270	<i>Date of accident:</i>	13/07/2019
<i>Year of Regn.:</i>	28/02/2017	<i>Date inspected:</i>	18/07/2019
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	26/07/2019

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.







































