

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/PA6282T/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PA6282T

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear bumper / 00	1	2,981.18	2,981.18
2.	Rear bumper bracket ? X nn	2	185.00	370.00
3.	Spray painting (two tone with faded effects)	1	600.00	500 600.00
4.	Labour charges	1	600.00	400 600.00
SUB-TOTAL				S\$4,551.18

- Price before 7% gst

1950
 - 19%
 1755

Steve (LKK) ML R
 21/6/21, 10:10am L/S

Thank you.

Yours faithfully,

Winnie Chai
 HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3 L/S
 My AL S/M
 P-1755
 L-900
 2655
 L/S-2124
 = 2190

1950/