Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.

Ltd.

AIG Building

78 Shenton Way #07-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

: S\$600.00

: 14

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur Date: 18 Jun 2021

Preliminary Advice

Vehicle No : SLQ7954U Accident Date : 17/06/2021 Make : KIA CERATO Policy No. : 1700031278

Assignment

Date

Date of

: 18/06/2021

: 18/06/2021 Est. Duration of

Excess

Inspection Repair

Inspection At: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS)

209 PANDAN GARDENS SINGAPORE 609339

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 19,209.20 **Revised Amount** :S\$ 15,309.20 :S\$ 2,640.00 Check Items (Estimated) Total :S\$ 17,949.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 58,000.00 COE / PARF Rebate :S\$ 35.823.00

Salvage Value :S\$

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :