

TP A16

Genia.

SJT2642K. 2009 Sept.

Kia Cendo Forte. 1591cc

KNAFU411MA5128170

Front Number Plate	Dented	30(SN) ✓
Front Number Plate Holder	Dehd	30(SN) ✓
Front Number Plate Garnish.	Dehd	40.30 ✓
Front Bumper	Dehd	585.40 ✓
Front Bumper Clips.	per	30(SN) ✓
Front Bumper Side Holder x 02	per	25.5 x 2 = 51 ✓
Front Bumper Lower Grille	cruld	72.50 ✓
Front Bumper Reinforcement?	per	243.60 ✓
Front Bumper Sponge.	per	92.40 ✓
Front Grille.	cruld	267.50 ✓
Front Grille clips	per	20(SN) ✓
Front Grille Logo	per	48 ✓
Headlamp x 02	LH cruld	522 x 2 = 1044 ✓ 522

SJT2642K.

Bonnet Dented 873.40 ✓

Bonnet Lock. ~~KL~~ 61.50. X

2460.10

S.N: 110.

2214.09

Panel Beating
Spray Painting.
Wiring.

~~600~~ 400

~~600~~ 400

~~50.~~ 30

830

Wht: 3154.09

2/s 2.5k.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: