

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

25/06/2021

01-43

Singapore 417883

Accident date : 20/06/2021

Estimated repair cost for vehicle no: SLW2200M MITSUBISHI ATTRAGE

CHASSIS: MMBSTA13AJH001426 (2017)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Neu</i>	\$708.60	+ \$708.60
2	1	REAR BUMPER SIDE RETAINER RH <i>Neu</i>	\$98.60	+ \$98.60
3	1	REAR TAILLAMP RH <i>graded</i> SVC	\$276.40	X \$276.40
4	1	REAR TAILLAMP INNER PANEL RH <i>Neu</i>	\$228.60	+ \$228.60
5	1	REAR TAILLAMP LOWER BRACKET RH	\$65.30	+ \$65.30
6	1	RH REAR FENDER <i>Distorted</i> 798	\$961.40	✓ \$961.40
7	1	RH REAR FENDER INNER PANEL <i>Regis</i>	\$556.40	+ \$556.40
8	1	RH REAR FENDER INNER TRIM BAORD <i>Neu</i>	\$334.50	+ \$334.50
9	1	RH REAR FENDER INNER SHIELD <i>Neu</i>	\$195.40	+ \$195.40
10	1	RH REAR DOOR <i>Dented</i>	\$831.00	✓ \$831.00
11	1	RH REAR DOOR INNER TRIM BOARD <i>Neu</i>	\$298.60	+ \$298.60
12	1	RH REAR DOOR BLACK STICKER <i>Neu</i>	\$78.10	✓ \$78.10
13	2	RH REAR DOOR HINGE <i>Neu</i>	\$55.80	+ \$111.60
14	1	RH REAR DOOR CHECKER <i>Neu</i>	\$32.60	+ \$32.60
15	1	RH REAR DOOR LOCK <i>Neu</i>	\$186.40	+ \$186.40
16	1	RH REAR DOOR OUTER HANDLER <i>Neu</i>	\$148.60	+ \$148.60
17	1	RH FRONT DOOR <i>Regis</i>	\$518.30	+ \$518.30
18	1	RH FRONT DOOR BLACK STICKER <i>Neu</i>	\$78.10	+ \$78.10
19	1	REAR WINDSCREEN GLASS MOULDING <i>Neu</i> 85	\$195.40	✓ \$195.40

TOTAL : \$5,611.80

LESS 10 % \$561.18

SUB-TOTAL : \$5,050.62

5313.51

2251.90

2026.71

2026.71

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR WINDSCREEN GLASS SEALANT <i>new</i>	\$120.00	<i>60</i> \$120.00
2	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	<i>+</i> \$80.00
3	1	REAR TAILLAMP CLIPS <i>new</i>	\$5.60	<i>2</i> \$5.60

60

TOTAL: \$205.60

TOTAL PARTS : \$5,256.22

Labour charges

1	LABOUR FOR PANEL BEATING	700 600	\$1,800.00
2	LABOUR FOR SPRAYPAINTING	650 600	\$1,200.00
3	WIRING CHECK	30	\$80.00
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	60	\$300.00
5	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	120	\$150.00
6	LABOUR FOR REMOVE & TRANSFER BOTH LH DOORS FITTING	80	\$300.00
7	LABOUR FOR REMOVE & REFIX LH UPHOLSTERY/ ROOF LINING	60	\$300.00

1550

Subtotal :- \$4,130.00

9649.11 Total:- \$9,386.22

L/s 07/07/21

05 Days

total: 3636.71

L/s 2.7K 2.7K

(2.7K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____