

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC21004664/T1vf3e2-1	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	07/07/2021	
			Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 7965P	Veh. Inspected	SMY 9699P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	20/21/21/VC05/024444	Excess (\$)	0.00	
	Assign From	ONG LI LI	Assign Date	22/06/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 420I COUPE	c.c	1997	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	WBA3N12050F994916	Colour	GREY	
	Odometer	157826 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/35 R19	MICHELIN	6 mm	
	L/H Front Tyre	245/35 R19	MICHELIN	6 mm	
	R/H Rear Tyre	245/35 R19	MICHELIN	6 mm	
	L/H Rear Tyre	245/35 R19	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/04/2021	Inspection Date	13/04/2021	
	Survey held at	GFORCE AUTOTECH PTD LTD			
		10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE SINGAPORE 417868			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				