

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Name : Dion Elizabeth Lim Bee Kim

Accident Date : 16-Jun-21

Vehicle No : FBM1181L

Vehicle Model : Honda CB150R
Manual

Estimated Repair Costs

Qty	Description <u>List Items</u>		Amount S(\$)
1	Front fender	11	\$ 175.00 X
1	Front fork - L/R/H	11	\$ 960.00 X
1	Front fork under bracket	11	\$ 255.00 X
1	Front rim shaft	11	\$ 68.00 X
1	Front wheel rim	11	\$ 850.00 X
1	Handle-bar	SC	\$ 155.00 X
2	Handle-bar ends	0/5 cu	\$ 128.00 AC
1	Hand grips (1 set)	1/11 111	\$ 80.00 X
1	Brake lever	SC	\$ 75.00
1	Front side mirror (1 set)	11	\$ 150.00
1	Trottle cable	11	\$ 145.00 X
1	Front footrest - R/H	cu	\$ 75.00
1	Front footrest bracket - R/H	11	\$ 245.00 X
1	Brake pedal	cu	\$ 95.00
1	Rear footrest - R/H	SC	\$ 70.00 X
1	Radiator side cover - R/H	SC	\$ 158.00
1	Tank side cover - R/H	TA R	\$ 300.00 X
			\$ 3,984.00
		Less 10%	\$ 398.40
			\$ 3,585.60

Not Authorised
LH

21/6/21

3 days

2/5 \$ 970

40

68

140

Special Net Items

1	Number plate (1 set)	11	\$ 28.00 X
2	Fork oils	11	\$ 30.00 X
2	Fork oil seals	11	\$ 56.00 X
1	Steering cone (1 set)	11	\$ 95.00 X
1	Rear food bag	TA R	\$ 280.00
1	Rear box bracket	R	\$ 180.00 X
			\$ 669.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Dion Elizabeth Lim Bee Kim

Accident Date : 16-Jun-21


Vehicle No : FBM1181L

Vehicle Model : Honda CB150R
Manual

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service(LOD)	\$	35.00 ✓
2	To check wiring and reset headlamp focusing	\$ 11	80.00 X
3	To respray paint	\$	200.00 180
4	To repair body frame	\$ 11	350.00 X
5	To provide labour	\$	400.00 200
		\$	1,065.00
Grand Total		\$	5,319.60

Singapore Dollars: Five Thousand Three Hundred Nineteen and Cents: Sixty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-578

102

2-518.40

5.2280

2 415

1213.4

202

970