

 **PREMIUM AUTOMOBILES**

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0508/2021/TF  
DATE : 22-Jun-21  
WIP : 32210

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/6/2021**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. NI SHUCHANG, KEVIN  
ADDRESS : BLK 28 WOODLANDS DRIVE 16  
#03-19  
SINGAPORE 737768  
TELEPHONE : HP +65 9477 5752  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070179107  
VEHICLE NO : SLJ 6090 E  
MODEL CODE : Q3 SPORTBACK 1.4 TFSI S tronic  
MODEL YEAR : 30/12/2020  
ENGINE NO : CZD C21588  
CHASSIS NO : WAUZZZF36M1054631  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 21-Jun-21  
PLACE OF ACCIDENT : BKE/KJE TOWARDS PIE



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJJ 6090 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	599 ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,700.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FENDERS, AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00 \$ X 500	2500 ✓
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, BOTH FRONT FENDER, HINGES, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 5,900.00 500 X 2 + 300	1500 <del>1400</del>
6	TO REAPPLY PAINT COATING FOR AFFECTED AREA. (BY OWNER)	S/N TBC	400 X 50 ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 15,472.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NDRA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 6090 E**

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER / 00	1	\$	2,815.00	2251.60	
2	FRONT BUMPER FIXING PARTS X nn	1	\$	414.00		
3	FRONT BUMPER CLOSING ELEMENT - LH / RH ? + nn	2	\$	118.00		
4	FRONT BUMPER CENTER TRIM (MANHATTAN GREY) ? x nn	1	\$	356.00		
5	FRONT BUMPER GRILLE - CENTER ? x nn	1	\$	217.00		
6	FRONT BUMPER SENSOR SUPPORT X nn	2	\$	50.00		
7	FRONT BUMPER LOWER COVER - CENTER X nn	1	\$	51.00		
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER X nn	1	\$	190.00		
9	FRONT BUMPER SPOILER X nn	1	\$	763.00		
10	FRONT BUMPER SPOILER BRACKET X nn	1	\$	21.00		
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ? x nn	2	\$	306.00		
12	FRONT BUMPER AIR GUIDE TRIM - LH / RH ? x nn	2	\$	328.00		
13	FRONT BUMPER SIDE SENSOR SUPPORT - LH / RH ? x nn	2	\$	50.00		
14	FRONT RADIATOR GRILLE / BR	1	\$	1,928.00	1542.40	
15	FRONT RADIATOR GRILLE STRIKER PLATE ? - BR	1	\$	244.00	194.80	
16	FRONT RADIATOR GRILLE LOGO COVER ? x nn	1	\$	56.00		
17	FRONT BUMPER BRACKET ? x nn	1	\$	41.00		
18	FRONT BUMPER SECURING PLATE ? x nn	1	\$	33.00		
19	FRONT RADIATOR GRILLE COVER ? - BR	1	\$	244.00	194.80	
20	FRONT CAMERA ? x M	1	\$	1,141.00		
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$</b>	<b>9,366.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 6090 E**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER CARRIER ? x nn	1	\$ 916.00	
22	FRONT BUMPER CARRIER FOAM ? x nn	1	\$ 102.00	
23	FRONT BUMPER GUIDE SECTION - LH / RH ? x nn	2	\$ 78.00	
24	FRONT BUMPER TOP COVER / BR	1	\$ 123.00	98.00
25	CAUTION STICKER / AK	1	\$ 14.00	10.88
26	A/C STICKER / AK	1	\$ 8.00	5.68
27	FRONT BUMPER PARKING AID SENSOR x nn	2	TBC	
28	FRONT BUMPER PARKING AID SENSOR SEAL / AK	4	\$ 16.00	
29	FRONT BUMPER WIRING SET ? - TN	1	\$ 572.00	479.20
30	HORN - LH / RH X nn	2	\$ 267.00	
31	HORN BRACKET - LH / RH X nn	2	\$ 44.00	
32	FRONT FENDER - LH / RH ? (photo) x nn	2	\$ 2,572.00	
33	FRONT FENDER ATTACHMENT PARTS X nn	1	\$ 63.00	
34	FRONT FENDER BRACE - LH / RH X nn	2	\$ 176.00	
35	FRONT FENDER BRACKET - LH / RH X nn	2	\$ 64.00	
36	FRONT WHEEL HOUSING LINER - LH / RH X nn	2	\$ 480.00	
37	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X nn	1	\$ 101.00	
38	FRONT BONNET / 00	1	\$ 3,508.00	2806.40
39	FRONT BONNET HINGE - LH / RH X nn	2	\$ 146.00	
40	FRONT BONNET ATTACHMENT PARTS X nn	1	\$ 296.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 9,546.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJ 6090 E**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	FRONT BONNET STRIKER - LH / RH X nn	2	\$ 220.00	
42	FRONT BONNET SOUND ABSORBER X nn	1	\$ 219.00	
43	FRONT BONNET INPACT PROTECTION / ACC	1	\$ 28.00	-21.84
44	FRONT BONNET LOCK (RH) - BT	X 1	\$ 427.00	170.80-
45	FRONT BONNET RELEASE ELEMENT X nn	1	\$ 58.00	
46	FRONT BONNET RELEASE LEVER X nn	1	\$ 14.00	
47	FRONT BONNET BOWDEN CABLE X nn	1	\$ 58.00	
48	FRONT BONNET BOWDEN CABLE COVER ? x nn	1	\$ 10.00	
49	FRONT HEADLIGHT MOUNTING - LH / RH ? - BR	2	\$ 236.00	-188.80
50	FRONT HEADLIGHT - LH / RH / CUT	2	\$ 11,178.00	-8942.40
51	FRONT HEADLIGHT LIFT CYLINDER - LH / RH ? x nn	2	\$ 420.00	
52	FRONT HEADLIGHT LIFT CYLINDER HOSE ? x nn	1	\$ 80.00	
53	FRONT WHEEL ARCH TRIM - LH / RH / ACC	2	\$ 1,072.00	-857.60
54	FRONT LOCK CARRIER / BR	1	\$ 1,272.00	-1017.60
55	A/C CONDENSER ? - DD	1	\$ 551.00	-440.80
56	TEMPERATURE SENSOR ? x nn	1	\$ 7.00	
57	ADDITIONAL RADIATOR ? x nn	1	\$ 920.00	
58	RADIATOR ? x nn	1	\$ 1,035.00	
59	COOLANT / Acc	6	\$ 266.00	-214.56
60	RADIATOR AIR GULDE- LH / RH / UPPER / LOWER ? - BR	1	\$ 160.00	59.61-
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 18,231.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 6090 E**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
61	FRONT TOP AIR GUIDE ? x nn	1	\$	56.00	
62	INTAKE AIR DUCT COVER x nn	1	\$	29.00	
63	INTAKE AIR GUIDE x nn	1	\$	20.00	
64	INTAKE AIR GUIDE HOSE x nn	1	\$	34.00	
65	FRONT NO. PLATE / OT	S/N	\$	60.00	60
66	SUNDRIES ? - nec		\$	400.00	12.80
<b>TOTAL SPARE PARTS</b>		:	\$	<b>37,742.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>15,472.00</b>	
<b>GRAND TOTAL</b>		:	\$	<b>53,214.00</b>	

**53,264.00**

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Steve (LKK)  
 SURVEYED DATE : 22/6/21, 11.10am  
 AUTHORISED DATE :  
 EXCESS COST :  
 LIABILITY :  
 REMARKS : P/P  
 My Bul sy  
 9 dys

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

JOHNNY BOO  
 BODY REPAIR MANAGER

ALLAN WU  
 CLAIMS CONSULTANT