



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM21006914/Ubs3q2 Date: 30/09/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 3897L	Veh. Inspected	SLX 9217P	
Policy No.	MR053REH104548265	Coverage (\$)	0.00	
Claim No.	S1M03CT4	Excess (\$)	0.00	
Assign From		Assign Date	22/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR HYBRID (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZYX102102570	Colour	WHITE	
Odometer	127161 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2021	Inspection Date	01/07/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	