

## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 21/06/2021
User ID : BoonChewTay

	Section A - Accident Det	talls	
egistration Number	SMB1337H		
ase Reference Number	BUS/06/21/1029		
tegistration Date	25/3/2013	a sale and the first sale and the sale and t	
company Type	SMRT Buses Ltd	The same transmitted to	
Make	MAN	The state of the s	
Model	A22	The state of the s	
Name of Driver	Nur Zaidani Bin Mohamad Zahir	torn appropriate the state of t	
Type of Accident	Head to Rear		
Accident Date and Time	17/6/2021 7:55 AM		
Accident Reported Date and Time	17/6/2021 9:15 AM		The second second
Is Surveyor Required?	No No	Al and the state of the state o	
Survey by	NEW YORK THE PROPERTY OF THE P	We will be a second of the sec	
Vehicle is Towed Back?	No 18 Y	William I was a second of the	
Towed Back Date and Time	A CONTRACTOR OF THE PROPERTY O		
Replacement Vehicle issued?	No	and the state of t	
Job Card Number	Part of the Property of March	a de Ora	
Special Instruction to ARC,if any	SMB1337H-REAR PORTION SMD668Z (TP) INSURED WITH		
Prepared Date and Time	21/6/2021 9:14 AM		
Chassis Number	WMAA22ZZ1D7001783	The state of the s	
Mileage			
Work Shop	17.		
Repair Completion Date and Time	The state of the s		
Repair Completion Date and Time	A STATE OF THE PROPERTY OF THE PARTY OF THE		
Repail Completion Date and Time	Section B - Summary of Repai	r Estimates	
market and the second s	Section B - Summary of Repai		
Summary of Repair Estimates	Section B - Summary of Repai	r Estimates Adjusted by Surveyor, if applicable	
Summary of Repair Estimates	Quotation from ARC		
Summary of Repair Estimates  Total Labour Cost	Quotation from ARC \$1,325.00	Adjusted by Surveyor, If applicable	
Summary of Repair Estimates  Total Labour Cost Total Spray Cost	Quotation from ARC \$1,325.00 \$446.00	Adjusted by Surveyor, if applicable  \$0.00	
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14	Adjusted by Surveyor, if applicable  \$0.00  \$0.00	
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00	
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031.14	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00	
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031,14 \$5,050.00	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00	
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031,14 \$5,050.00	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00	Den and the state of the state of the sense
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031,14 \$5,050.00 4.0 Boon Chew Tay	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00	he depaire: of the fall cuin -
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031,14 \$5,050.00	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00	ne depaire: of the following: To resultary before one or
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031,14 \$5,050.00 4.0 Boon Chew Tay	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00	The Repaire: of mar following: To result of the baller of as an indicate of the special of the s
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031,14 \$5,050.00 4.0 Boon Chew Tay	Adjusted by Surveyor, If applicable  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00	The Repairer of the followings:  To result of the Sale of the followings:  To desplay demographs:  The desplay demographs:  The desplay demographs:  The desplay demographs are the sale of the demographs.
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature  Remarks	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031,14 \$5,050.00 4.0 Boon Chew Tay	Adjusted by Surveyor, If applicable  \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00  \$0.00	The repaire: of the following: To result of the solder of the following of the solder of the following of the solder of the following of the solder of the s
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature  Remarks	Quotation from ARC \$1,325.00 \$446.00 \$2,780.14 \$480.00 \$5,031.14 \$5,050.00 4.0 Boon Chew Tay 21/06/2021 9:17 AM	Adjusted by Surveyor, if applicable  \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00  \$1.00 \$1.0	The repaire: of the following: To result, the head of the milder of the



## **SMRT Accident Vehicle Repair Estimates**

C. Har

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/06/2021
User ID : BoonChewTay

Control of		AND THE PARTY OF T	Market Market Market Market	OF PARTY		- Wallett Daniel	NAME OF TAXABLE PARTY.	Mark Works	Control Lawrence Control Control
Part 1 - Lat	our Works		Sect	ION D - Det	ails of Repair I	estimates	STORY TOWN	<b>新疆域的是北极</b>	
	oui Works								
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,325.00				1066		
Total Labour			\$1,325.00				1000		
Part 2 - Spr	ay Painting &	Panel Beating Rel	ated Works						70
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$446.00				441.		
Total Spray Painting & Panel Beating			\$446.00	The second second	90,0	N 4 5 1 1 10	/ ( V		
Part 3 - Othe	r Costs - Acc	Ident and Acciden	t Repair Related Expen	80	No. of the second	S R Dec 2	No Chronical States	San agreement and the second	Office surgest the study Land
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
ADVERTISEMENT STICKER Total Other Costs			\$480.00				480		
			\$480.00						
Part 4 - Spar	e Parts / Mate	erial Usage		March March	<b>克勒斯</b> 斯 (1000年)	er and protection of	a TRANSP Serret The Co	SAME OF THE PARTY OF	TO PERSONAL SECTION
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010464	VM	S01001-CW002	BRACKET,ATTACHMEN T:FOR MAN A22 BUS	1.00	\$569.30	10.00	\$512.37	Replace	repor
6010463	Body	S01001-CW006	FRAME,REAR BUMPER:FOR MAN A22 BUS \	1.00	\$1,423.20	10.00	\$1,280.88	Replace	64/
010064	Body	F01001-CW274	BUMPER:REAR,CENTR E,FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	der
otal			in the Market and the	the same of	\$3,861.30	150	\$3,475.17		
dded Spare	Parts / Materi	ial Usage After Su	rveyor Signed off		t vine		NEW YORK	L	
art Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
otal	DATE OF THE PARTY	A STATE OF THE STA	Committee Specification (Co. 1946)	Maria A. Carl - Con-	ATH DESCRIPTION STATES	terración dendicións		STATE OF THE PARTY	THE PERSON NAMED IN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Para 49 00010068
3 days
45
21/06/21 @1420
Para after reporter