

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLU1302U (Insd veh)	Model:	TOYOTA HIACE 3.0 D TURBO 5
	GBF2148P (TP veh)		DR (M)
Date of Accident:	21/06/2021		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No
Repair Estimate	: \$	29,309.07	
Final Repair Cost	: \$	10,800.00	
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$	10	days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$	10,800.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> [] YES <input checked="" type="checkbox"/> [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Xin Hua Workshop Pte Ltd	: \$	10,800.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

15 Jul
2022

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))