

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ✓	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	----------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref: CS/TMI21006948/Atf3		
20 MCCALLUM STREET #09-01		Date: 23/06/2021		
TOKIO MARINE CENTRESINGAPORE 069046		Code: TMI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMZ 8874B	Veh. Inspected	SMC 4112P	
Policy No.	MM000365	Coverage (\$)	0.00	
Claim No.	M2102869	Excess (\$)	0.00	
Assign From	MERIMEN (ONG CHIN KIAT)	Assign Date	23/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/06/2021	Inspection Date	18/06/2021	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				