



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TANG KAH PING	Cust No/Name /TANG KAH PING
336 BUKIT BATOK STREET 32	Reg No/Reg Date SMV9778K / 29/10/202
#09-299	Date In/Mileage / 0
SINGAPORE 650336	Chassis No JMAXTGK1WLZ000785
Contact No Mobile: 82626300	Engine No 4B40HB6423
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR
	Colour/Trim P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	23/06/2021/ 12:35	BLC	442 / CocoLu	12328			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								
RENEW REAR BUMPER, TAILGATE, REAR END PANEL, LAMP HOUSING LH								4480.00
REPAIR REAR FENDER LH,								
E PNT88000								
REMOVE & INSTALL TAILGATE TOP GLASS								300.00
E PNT88000								
REMOVE & INSTALL TAILGATE LOWER GLASS								300.00
E PNT88000								
REMOVE & INSTALL TAILGATE TRIMS AND REAR COMPARTMENT TRIMS								400.00
E PNT88000								
REMOVE & INSTALL PARKING SENSOR								80.00
E PNT88000								
REMOVE & INSTALL REVERSE CAMERA								150.00
E PNT98000								
SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR FENDER LH,								3850.00
REAR LAMP HOUSING LH, REAR END PANEL, SPOILER,								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								280.00
USING HI-SCAN PRO TEST								
A 90000001								
CHECK WIRING & ELECTRICAL SYSTEM								30.00
M SUNDRY								
APPLY SEALANT FOR TAILGATE BOTH GLASS								160.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								120.00
M SUNDRY								
C&C LOGO								40.00
M SUNDRY								
PAINT PROTECTION FOR ACCIDENT AFFECTED AREA								750.00
M SUNDRY								
REAR BUMPER PLATE WITH FRAME								50.00
M SUNDRY								
REAR IN CAR CAMERA								680.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TANG KAH PING	Cust No/Name /TANG KAH PING
336 BUKIT BATOK STREET 32	Reg No/Reg Date SMV9778K / 29/10/202
#09-299	Date In/Mileage / 0
SINGAPORE 650336	Chassis No JMAXTGK1WLZ000785
Contact No Mobile: 82626300	Engine No 4B40HB6423
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR
	Colour/Trim P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	23/06/2021/ 12:35	BLC	442 / CocoLu	12328			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								240.00
TAILGATE TOP GLASS FOLAR FILM								
M SUNDRY								240.00
TAILGATE LOWER GLASS FOLAR FILM								
M SUNDRY								20.00
Sundry								
A 54900099								300.00
REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR								
A 54900099								300.00
RENEW EXHAUST MUFFLER ASSY								
M SUNDRY								120.00
TOWING FEE								
M FACE,RR BUMPER					1.00	556.00	00.00	556.00
M EXTENSION,RR BUMPER					1.00	152.00	00.00	152.00
M COVER,RR BUMPER,RH					1.00	117.00	00.00	117.00
M COVER,RR BUMPER,LH					1.00	117.00	00.00	117.00
M BRKT,R/BMPR FACE SIDE,RH					1.00	25.00	00.00	25.00
M BRKT,R/BMPR FACE SIDE,LH					1.00	25.00	00.00	25.00
M BRACKET,RR BUMPER SIDE,LWR					1.00	12.00	00.00	12.00
M REINFORCEMENT,RR BUMPER					1.00	497.00	00.00	497.00
M CORE,RR BUMPER					1.00	34.00	00.00	34.00
M CORE,RR BUMPER					1.00	41.00	00.00	41.00
M EXTN,QTR PANEL,RR LWR LH					1.00	97.00	00.00	97.00
M REINF,GATE PILLAR,LH					1.00	150.00	00.00	150.00
M PANEL,QTR,OTR LH					1.00	866.00	00.00	866.00
M PANEL,RR END					1.00	475.00	00.00	475.00
M PANEL,RR END,INR LH					1.00	137.00	00.00	137.00
M PANEL,RR END,INR RH					1.00	137.00	00.00	137.00
M BRACE,RR FLOOR SIDE,LH					1.00	33.00	00.00	33.00
M SHIELD,RR WHEEL,RR LH					1.00	38.00	00.00	38.00
M PANEL ASSY,TAILGATE					1.00	984.00	00.00	984.00
M HINGE,TAILGATE					2.00	29.00	00.00	58.00
M GAS SPRING,TAILGATE,RH					1.00	148.00	00.00	148.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TANG KAH PING	Cust No/Name /TANG KAH PING
336 BUKIT BATOK STREET 32	Reg No/Reg Date SMV9778K / 29/10/202
#09-299	Date In/Mileage / 0
SINGAPORE 650336	Chassis No JMAXTGK1WLZ000785
Contact No Mobile: 82626300	Engine No 4B40HB6423
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR
	Colour/Trim P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	23/06/2021/ 12:35	BLC	442 / CocoLu	12328
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M GAS SPRING, TAILGATE, LH		1.00	148.00	00.00	148.00
M W/STRIP, TAILGATE OPENING		1.00	194.00	00.00	194.00
M GLASS, TAILGATE WINDOW		1.00	706.00	00.00	706.00
M FASTENER, WINDSHIELD		8.00	6.00	00.00	48.00
P STOPPER, WINDSHIELD GLASS		2.00	3.00	00.00	6.00
P SPACER, QTR WINDOW		2.00	8.00	00.00	16.00
M SPACER, QTR WINDOW		2.00	8.00	00.00	16.00
P SPACER, TAILGATE		2.00	8.00	00.00	16.00
P SPACER, TAILGATE		2.00	8.00	00.00	16.00
M DAM, TAILGATE, LWR		1.00	13.00	00.00	13.00
M GLASS, TAILGATE WINDOW		1.00	524.00	00.00	524.00
M GARNISH, TAILGATE		1.00	490.00	00.00	490.00
M LATCH, TAILGATE		1.00	385.00	00.00	385.00
M HANDLE, TAILGATE LOCK RLSE		1.00	201.00	00.00	201.00
M TRIM, TAILGATE, LWR		1.00	402.00	00.00	402.00
M MOULDING, R/DOOR PROTECT, LH		1.00	105.00	00.00	105.00
M GARNISH, QTR PANEL, LH		1.00	181.00	00.00	181.00
M MARK, ECLIPSE CROSS		1.00	87.00	00.00	87.00
M MOULDING, RR WHEEL ARCH, LH		1.00	153.00	00.00	153.00
M TRIM, RR SHELF		1.00	578.00	00.00	578.00
M TRIM, RR END		1.00	122.00	00.00	122.00
M LID, CARGO FLOOR BOX		1.00	324.00	00.00	324.00
M LAMP ASSY, COMB, RR LH		1.00	693.00	00.00	693.00
M LAMP ASSY, COMB, RR RH		1.00	693.00	00.00	693.00
M LAMP ASSY, STOP & TAIL		1.00	1118.00	00.00	1118.00
M LAMP ASSY, BACKUP, LH		1.00	118.00	00.00	118.00
M LAMP ASSY, LICENSE PLATE		1.00	34.00	00.00	34.00
M LAMP ASSY, FOG, RR RH		1.00	132.00	00.00	132.00
M MOTOR, RR WINDOW WIPER(*)		1.00	462.00	00.00	462.00
M BLADE ASSY, RR WINDOW WIPER		1.00	32.00	00.00	32.00
M ARM ASSY, RR WINDOW WIPER		1.00	44.00	00.00	44.00
M BUZZER, KEYLESS OPERATION, RR		1.00	91.00	00.00	91.00
M ANT, KEYLESS OPERATION, RR		1.00	96.00	00.00	96.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TANG KAH PING	Cust No/Name /TANG KAH PING
336 BUKIT BATOK STREET 32	Reg No/Reg Date SMV9778K / 29/10/202
#09-299	Date In/Mileage / 0
SINGAPORE 650336	Chassis No JMAXTGK1WLZ000785
Contact No Mobile: 82626300	Engine No 4B40HB6423
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR
	Colour/Trim P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	23/06/2021/ 12:35	BLC	442 / CocoLu	12328
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M SENSOR, BACK DISTANCE WARN		1.00	329.00	00.00	329.00
M SENSOR, CORNER CLEARANCE		1.00	333.00	00.00	333.00
M SENSOR, CORNER CLEARANCE		1.00	333.00	00.00	333.00
M HARNESS, RR BUMPER		1.00	220.00	00.00	220.00
M HARNESS, TAILGATE		1.00	306.00	00.00	306.00
M CAMERA, RR VIEW		1.00	681.00	00.00	681.00
M DUCT, RR VENTILATOR		1.00	39.00	00.00	39.00
M MUFFLER, EXHAUST MAIN		1.00	600.00	00.00	600.00

# Estimate

Confirm &amp; accepted by

Nett 28,674.00  
 7% GST on 28674.00 2007.18

**Total Payable 30,681.18**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.