



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006954/Nqf3e2	
			Date: 04/05/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 5856J	Veh. Inspected	SLD 3727D
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/21/2039	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	23/06/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA VEZEL 1.5X	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU31202414	Colour	BLUE
	Odometer	69051 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/65 R15	YOKOHAMA	5 mm
	L/H Front Tyre	205/65 R15	YOKOHAMA	5 mm
	R/H Rear Tyre	205/65 R15	FIRENZA	5 mm
	L/H Rear Tyre	205/65 R15	FIRENZA	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/06/2021	Inspection Date	23/06/2021
	Survey held at	56 LOYANG WAY #04-04		
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	