

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD			Ref:	CS/SMR21006954/Nuf3
60 WOODLANDS INDUSTRIAL PARK			Date:	23/06/2021
E4SINGAPORE 757705			Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 5856J		Veh. Inspected	SLD 3727D
Policy No.			Coverage (\$)	0.00
Claim No.	TAX/06/21/2039		Excess (\$)	0.00
Assign From	HUA YEN		Assign Date	23/06/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/06/2021		Inspection Date	23/06/2021
Survey held at	56 LOYANG WAY #04-04			
Repairer	AP AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				