

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0511/2021/ZK
DATE : 22-Jun-21
WIP : 32219

Xiao Tony

\$3226.80

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 23/6/2021
YOUR INSURED VEH NO : SMQ 1942 G

DIRECT ASIA INSURANCE(SG) PTE LTD
88 SOUTH BRIDGE ROAD
SINGAPORE 058716
SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPT
TEL: 6880 4602 - FAX: 6880 4838

OWNER'S NAME : SEOW CHUI HOON ALICE
ADDRESS : BLK 407 BEDOK NORTH AVE 3
#16-179
SINGAPORE 460407
TELEPHONE : HP +65 96271186
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00886259
VEHICLE NO : SKS 209 K
MODEL CODE :
MODEL YEAR : 30/12/2020
ENGINE NO : CZD C15328
CHASSIS NO : WAUZZZF38M1041380
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Jun-21
PLACE OF ACCIDENT : 475 CHANGI ROAD S(419892)

PREMIUM AUTOMOBILES



55 URI RAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 209 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID REAR LID KICK SENSOR	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.	\$ 1,200.00	500
3	TO RESPRAY REAR BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS.	950 \$ 2,800.00	550 Wheel Arch x 2 = 400 950
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,552.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

MAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 209 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1 S	1,634.00	+
2	REAR BUMPER SPOILER <i>Distorted</i>	1 S	459.00	✓ 367.20
3	REAR BUMPER GRILLE - LH <i>new</i>	1 S	152.00	+
4	REAR ULTRASOUND SENSOR BRACKET - LH <i>new</i>	1 S	25.00	+
5	REAR BUMPER CROSS REINFORCEMENT - CENTER <i>new</i>	1 S	97.00	+
6	REAR BUMPER BRACKET - CENTER <i>new</i>	1 S	48.00	X
7	REAR LIGHT REFLECTOR - LH <i>new</i>	1 S	41.00	+
8	REAR BUMPER CARRIER <i>new</i>	1 S	651.00	X
9	REAR BUMPER HOLDING STRAP - LH / RH <i>new</i>	1 S	58.00	X
10	REAR BUMPER SHOCK ABSORBER <i>new</i>	1 S	85.00	+
11	REAR PARKING AID SENSOR <i>new</i>	1	TBC	+
12	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4 S	14.00	+
13	REAR WHEEL COVER - LH / RH <i>new</i>	2 S	1,072.00	✓ 857.60
14	PACKING ADHESIVE <i>new</i>	1 S	19.00	+
15	AUDI EMBLEM <i>new</i>	1 S	138.00	+
16	Q3 EMBLEM <i>new</i>	1 S	99.00	+
17	SUNDRIES <i>new</i>	S/N S	250.00	X
TOTAL SPARE PARTS		:	\$	4,842.00
TOTAL LABOUR CHARGES		:	\$	4,552.00
GRAND TOTAL		:	\$	9,394.00

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *23/06/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 03 days*
[Signature]

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHN NY BOO
BODY REP/ IR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: