

COMFORTDELGRÖ ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4469P

DATE: 22. June 2021

MAKE HYUNDAI

MODEL IONIQ

DOA: 22. Jun. 2021

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	BOOTLID COVER			\$2,480.40
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MLDG			\$451.25
10	REAR BUMPER CLIP			\$22.00
1	REAR BUMPER BEAM			\$394.80
1	REAR FOG LAMP			\$201.50
1	ANTENNA – SMARKKEY			\$40.50
1	BOOTLID EMBLEM – IONIQ			\$31.30
1	BOOTLID EMBLEM – H			\$28.00
1	BOOTLID EMBLEM – HYBRID			\$24.30
1	REAR WINDSCREEN SEALANT			\$46.00
SUB TOTAL				\$4,179.45
LESS 25%				\$839.49
DISCOUNTED TOTAL				\$3,357.96
WINDSCREEN SEALANT				
	REVERSE SENSOR			\$180.00
	REAR BUMPER MAT			\$50.00
	BOOTLID COMFORTDELGRO LOGO			\$30.00
	BOOTLID TEL.NO STICKER			\$30.00
	BOOTLID APPS LOGO			\$40.00
				\$330.00
Labour Charge				
	PANEL BEATING			\$900.00
	SPRAY PAINT			\$600.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	RENEW REAR WINDSCREENGLASS			\$120.00
TOTAL LABOUR				\$1,700.00
ESTIMATE TOTAL				\$5,387.96
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

DD

CRK

CRK

NEC

?

XSVL

?

NEC

NEC

NEC

NEC

NEC

Nett

Nett

Nett

NEC

NEC

NEC

700

500

30

80

LKK Auto Centre will review with the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAZ LKK
23/6/2021 1600
30905 RH

CHECK ITEM PHOTO
BY PAW PHOTO