

Claim Audit

AUDIT TRAIL			
No.	On	Audit	Remarks
1	18 Jun 2021 00:30	Clm Veh Model Changed	
2	18 Jun 2021 00:30	Clm Created	Reg No: SJE3277D. Policy No: 1800149049-02. Acct Date: 2021/06/17. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R216H0007
3	21 Jun 2021 12:11	Clm Registration Modified	Pol No:1800149049-02->1800149049. Init.Est.:>5,000 - 6,000.
4	21 Jun 2021 12:13	Clm Veh Model Changed	(206863) AUDI A4 2.0 TFSI S-TRONIC (A).
5	24 Jun 2021 11:26	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.
6	24 Jun 2021 11:26	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)
7	24 Jun 2021 11:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):
8	24 Jun 2021 11:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/07/05
9	24 Jun 2021 11:26	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.
10	24 Jun 2021 11:26	Clm Registration Modified	Rep:1137->200611.
11	24 Jun 2021 11:27	Adj Adjuster Assigned	[None] -> ADRIAN LING
12	24 Jun 2021 13:41	Clm Registration Modified	2F Remarks: -> Not Applicable. GST: -> 7.00.
13	24 Jun 2021 14:28	Adj Rpt Initiated	
14	24 Jun 2021 14:28	Clm Dtl Modified	Claim Conclusion: -> 3.
15	24 Jun 2021 14:28	Clm Dtl Modified	JPJ Reg. Date: -> 2018/12/24.
16	24 Jun 2021 14:28	Clm Details Notified	

AUDIT TRAIL

No.	On Audit	Remarks	By
17	24 Jun 2021 15:00 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/07/05	[A] SHIAU CHAN
18	24 Jun 2021 15:00 Adj Mandate Request	Cur.Req:2935.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NO T AUTHORISE REPAIR.	[A] SHIAU CHAN
19	25 Jun 2021 08:38 Clm Registration Modified	Excess: -> 550.00. Excess Waived: -> 550.00.	[I] Azlan, Syazairdina
20	25 Jun 2021 09:36 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/07/05. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repa	[I] Lim, Kok-Chong
21	25 Jun 2021 09:36 Adj Mandate Set	Approved:2635.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for a ll NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From




Date To




Audit Type



ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2704015	24 Jun 2021 14:28:19	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJE3277D		11.00