COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE*

VEHICLE NO

Date:

SHA7104M

MAKE

HYUNDAI

HIONDA

DATE:

23. June 2021

Jumani

MODEL IONIQ **ECICS** DOA: 23. Jun. 2021 Qty Parts Description/Labour Type **Unit Price Amount** DEF **1 REAR BUMPER TOW COVER** \$98.80 1 REAR BUMPER ASSY \$459.40 1REAR BUMPER CENTRE MLDG \$451.25 / CRIC 10 REAR BUMPER CLIP \$22.00 / 1/2 6 1REAR BUMPER BEAM \$394.80 1 REAR FOG LAMP \$201.50 1ANTENNA – SMARKKEY \$40.50 \$1,668.25 \$1,668.25 **SUB TOTAL LESS 25%** \$333.65 **DISCOUNTED TOTAL** \$1,334.60 WINDSCREEN SEALANT \$180.00 Nett / DEF REVERSE SENSOR REAR BUMPER MAT \$50.00 Nett NEC \$230.00 Labour Charge 350 PANEL BEATING \$400.00 250 SPRAY PAINT \$300.00 REMOVE/REFIX REVERSE SENSOR \$80.00 30 \$780.00 **TOTAL LABOUR** LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting \$2,344.60 **ESTIMATE TOTAL** To display damaged part(s) during resurvey · Parts prices are subject to confirmation . Third party survey is on a "Without Prejudice" basis · No illegal modification(s) is allowed entary item(s) must be resurveyed and Is subject to final approve from insurance Company of a visual inspection of the above vehicle. The final repair quantum will Acknowled by Branced after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZILE Z416/1021 \$ 1545

PIP/2 DAW)

CHICK STEMPHOTOS

AFTEL REPAR EHOTOS