Our Job Ref Date		305475091 23/07/21		Com 59 Lo Fax:	OMFORTDELGRO NGINEERING fortDelGro Engineering Pie Ltd oyeng Drive Singapore 508989 6546 6156	
To :		LKK		Fax:		
Attn : Mr		NAZ			23.06.21	
	No. : SHA					
The survey a	and estimates of	the repairs of the above-me	ntioned vehicle	are as follows	3:-	
1. The n	spair job shall bi	II to:	AIG	•••	SJA4473T	
	nalized amount					
		er List discount				
(a)	Labour Charge					
(b)		By-Part Repair Cost				
	(Otal for Care)					
(c.)	Lumpsum Reportation of Lumpsur Final Lumpsur	air (if applicable) sum repair cost after Less: m Repair cost	20%	-	\$6,750.00 \$6,	god, 00
4. We sh	ated normal peri nall treat the ab ng days	od for repairs:ove amount as Correct and	Confirmed if			
5. Thank	you for your as	sistance.		e confirm the e alized amount		
Signat Name Tel Fax		55	_ Siç	gnature:	NAZ LEE 13/8/2021	
For Official (Jse Only					•
	tem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Rental Ra	te P/Day		YES			
2. Loss of In			NO			
3. Survey Fe						
4. LTA Searc		\$7.49 / \$2.00				
Medical For of driver, if	ees (on behalf applicable)					
6 Overrun						

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3306Z

Make : Toyota

Model : Prius (G4)

Date: 24.06.2021

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount	/TN
				\$198.50	
1	1 FRT FENDER SHIELD			\$945.30	/DD
1	1 FRONT FENDER SUB ASSY 1 FRONT FENDER HOUSING LH			\$958.30	SXSO (
1	1 FRT FENDER SHIELD CLIPS			\$30.00	/ NEC
1	1 FRONT FENDER HYBRID EMBLEM LH				MEL
1	1 FRT PILLAR UPPER LH				?XSVL
	FRONT BUMPER COVER			\$499.90	/ CRK
1	FRONT BUMPER SIDE BRACKET LH			\$82.30	SXZOF
l .	FRONT BUMPER CLIPS			\$22.00	JNEC JNEC
1	FRONT BUMPER SIDE COVER LH			\$172.50	•
1	FRONT BUMPER CENTRE GRILLE			\$301.90	1 1200
	FRONT BUMPER LOWER GRILLE			\$166.90	SXCOL
	FOG LAMP LH			\$920.00	1 ckl
1	FRONT BUMPER SIDE RETAINER LH			\$77.00	/ CRX
	HEADLAMP UNIT ASSY LH			\$2,735.28	/ SCR
1	HEADLAMP PANEL LH			\$240.10	
	TOP PANEL SIDE LH			\$145.90	? XSUC
1	FRT SUSPENSION LOWER ARM LH			\$637.50	3 XSVC
1	FRT SHOCK ABSORBER LH			\$401.80	?/DEF
1	ABSORBER TOP MOULDING LH			\$196.20	? K5UC
1	STABILIZER BAR LH			\$360.00	SXZOC
1	STABILIZER LINK LH			\$199.00	? - DEF
1	LOWER BALL JOINT LH			\$199 98	3/DEL
1	TIE ROD END LH			\$159.30	? - DEF
1	KNUCKLE STEERING LH			\$580.80	3/DEF
	FRT WHEEL RIM LH			\$1,570.55	4 0
'	TRI WILLE NIW E.				
	CUR TOTAL		9,194.01	¢11 001 51	
	SUB TOTAL LESS 25%		70%	\$11,991.51 \$2,997.88	1
				\$8,993.63	4
	DISCOUNTED TOTAL	1	6,895,50	\$0,993.03	4
				2.5/	/GRAZED
	FRT TYRE LH		151,20	30% \$216.00	
	Labour Charge Towing fee (c	nn atta	goved)	\$ 60	
1	PANEL BEATING			\$1,750.00	7.00
1	SPRAY PAINTING CHARGE			\$600.00	500
	WIRING CHARGE			\$50.00	30
	TUFF KOTE			\$60.00	40
1	FRT WHEEL ALIGNMENT			\$80.00	?XNN
1 1	REMOVE & REFIX FRT UNDECARRIAGE				42 8150
' '		•	1,420		4130

6,800,00

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	TOTAL LABO	UR		\$2,940.0
	ESTIMATE TO	ΓAL		\$12,149.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ CKK 241612021 1535 LIS 4 DMS CHECK ITEM PHOTOS AFTER FERME PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

VEHICLE I	SHA3306Z	TYPE OF C:	TP
	AIG	SURVEY B':	LKK/NAZ
	305475091	DATE :	28/06/2021

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMAT	E \$	REMARKS
WHEEL HUB BEARING LH	1		\$560.10	NEC
		TOTAL	\$560. 10	