

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/518/2021/GW
DATE : 23-Jun-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS SIVALINGAM BHAVANI MRS.BHAVANI KATZMANN
ADDRESS : 29 ANGULLIA PARK
#16-01, ORCHARD VIEW
SINGAPORE 239977
TELEPHONE : HP +65 97355974
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100477186-04
VEHICLE NO : **SLE 6126 M**
MODEL CODE : A3 SB 1.4 TFSI
MODEL YEAR : 27/7/2016
ENGINE NO : CZC563903
CHASSIS NO : WAUZZZF8V5GA168199
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-21
PLACE OF ACCIDENT : CARPARK AT 6 EU TONG SEN ST

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 6126 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X NN
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	/
3	DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	S/N \$ 2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER,	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 5,002.00	2642

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 6126 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / cut	1	\$ 2,016.00	✓ 1612.8
2	FRONT BUMPER FIXING PARTS X NN	1	\$ 187.00	
3	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE X NN	2	\$ 156.00	
4	FRONT BUMPER GUIDE SECTION RH - NBL	1	\$ 63.00	✓ 50.32
5	FRONT BUMPER AIR GUIDE GRILLE RH X NN	1	\$ 109.00	
6	FRONT FENDER RH / Buc	1	\$ 851.00	✓ 680.4
7	FRONT FENDER ATTACHMENT PARTS X NN	1	\$ 72.00	
8	FRONT FENDER BRACKET RH X NN	1	\$ 48.00	
9	FRONT FENDER CLOSING ELEMENT RH ✓ BT	1	\$ 62.00	✓ 48.88
10	FRONT FENDER BRACE RH X NN ✓ BT	1	\$ 96.00	✓ 76.48
11	FRONT FENDER POP RIVET - NBL	8	\$ 27.00	✓ 21.12
12	FRONT WHEEL HOUSING LINER RH X NN	1	\$ 169.00	
13	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X NN	1	\$ 89.00	
14	HEADLIGHT RH / cut	1	\$ 2,641.00	✓ 2112.8
15	LIFY CYLINDER FOR HEADLIGHT WASHER SYSTEM X NN	1	\$ 193.00	
16	HOSE FOR HEADLIGHT WASHER SYSTEM X NN	1	\$ 182.00	
17	SUNDRIES X NN		\$ 300.00	
TOTAL SPARE PARTS			\$ 7,261.00	4602.8
TOTAL LABOUR CHARGES			\$ 5,002.00	
GRAND TOTAL			\$ 12,263.00	7244.8

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Eric Qian
82880282

: 2526/6/21.

: Not Authorised.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

4 Days.

before paint photo's.

Excess : TBA.

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: