

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref: CS/III21007064/Kqf3	
64 CECIL STREET			Date: 28/06/2021	
#05-02 IOB BUILDING SINGAPORE 049711			Code: III2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected GBE 8096X		
Policy No.		Coverage (\$) 0.00		
Claim No. MCV2021D0002754		Excess (\$) 0.00 3100		
Assign From BHUVANESWARI		Assign Date 28/06/2021		
2. Vehicle Particulars & Condition				
Make & Model		c.c 0		
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 24/06/2021		Inspection Date 28/06/2021		
Survey held at		CT AUTO PTE LTD		
		160 SIN MING DRIVE		
		#02-14 SIN MING AUTOCITY		
		SINGAPORE 575722		
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE)				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				